WASHINGTON COUNTY OREGON
Nw 311 st
North-South Road Name

ADA Curb Ramp New Construction Inspection Form (Parallel)

Nw 311 st	24952.54		Nw comme	ercial st		
North-South Road Name	Project No. Shee	t No. Intersection No. E	ast-West Ro		oregon.gov/odot/Engine	
	Calibration Da	ate 8/30/2024 (mm/dd/yy)			g/ADA_ExhibitA.pdf for m gton County corner num	
PL	RAMP RUN 1	Pass	Fail	3	Carnor	2
Ramp Style	Running Slope 1	1.8 ≤ 2.0% ■ > 2.0)% []	Corner Position	Corner Positions	7
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	0.5 ≤ 2.0% ■ > 2.0)%	Position 3	5	2A
depends on the Intersection Control Type. At a	Detectable Warning	Y N				3
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	≤ 1/4"	1"	3A	1	*
must be \leq 5.0%, and at Stop	Gutter Flow Slope	0.9 < * > *		2	North	2
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	1.1 ≤ 8.3% > 8.3	3%>		(11
* ¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	3.9 ≤ 5.0% > 5.0%	0%	1 4 2	Ramp 1 Positions	
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of r	amp Y N		Ramp Position	5	
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass	Fail		PE Stamp (required for
	Running Slope 2	≤ 8.3% ■ > 8.3	3%		private dev	velopment)
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Length 2	11.55				
(mets, ungiment, etc.)	Cross Slope 2	≥ 2.0% ≥ 2.0%)% ■			
~~ **	RAMP RUN 3	Pass	Fail			
15 Pag 3 15 15 15 15 15 15 15 15 15 15 15 15 15	Running Slope 3	≤ 8.3% > 8.3	3% 🗌			
To Plan 2 Page 2	Length 3	9.3				
	Cross Slope 3	2.2 ≤ 2.0% > 2.0	0% 🔳 📙			
Counter slope	TURN SPACE	Pass	Fail	Comments:		
	Width X	5.0 ≥ 4.0' ■ < 4.0	0'			
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 ■ < 4.0)'* ¹			
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 < 5.0)'* ¹			
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	0.5 ≤ 2.0%	0% 🗌 🗎			
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	1.8 ≤ 2.0% ■ > 2.0	0% 🔲			
Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail	Inspector's Signature		Date (mm/dd/yy)
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	≥ 4.0' < 4.0	0' 🔲 🛚	Darrell Wyant		52638
	Intersection Control Type	SY Slope of Rd. 0.9	9	Print name clearly		Certification No
Gutter Flow Slope (as directed)	Horizontal Gaps	≤ 1/2" > 1/	'2"	3J Consulting		
	Tiorizonital Gaps	- 1/2 / 1/	-	Company/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





