

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	20121							
N	lw Kaye way	24952.54				Nw m	ays s	st
No	orth-South Road Name	Project No. Shee	et No. In	tersection N	o.	East-W	est Ro	pad Name
		Calibration Date	8/6/2024	(mm/dd,	/yy)			k - ') · · · · · · · · · · · · · · · · ·
	Ramp Style PR	RAMP RUN 1		≤ 8.3%	Pass	>8.3%	Fail	2 Corner
The pass	ssing value for Gutter Flow Slope (GFS) s on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at ed or Uncontrolled (SU), GFS must be ≤	Running Slope 1 Length 1	19.3	20.370		5.5.		Corner Position 3 Positions 2A
•		Cross Slope 1		≤ 2.0%		>2.0%		200
Signalize		Detectable Warning (Y,N)		Y		N		3A 1
5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.		Lip Height		1/4"		>1/4"		2 North
	of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope	'A 2.1	≤ *		>*		
		Curb Running Slope (avg)	1.12	≤ 8.3%		>8.3%		Ramp 4 Positions 1
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	5	≤ 5.0%		> 5.0%		Position 5
	o <u>Standard Drawings</u> to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	0.4	< 5.0'		≥ 5.0'		PE Stamp (requir private developm
/	X 7	Detectable warning extends full width of ramp throat opening		Υ		N		
Counter slope Guiter Flow slope		TURN SPACE LANDIN	G NON	E	Pass		Fail	
		Width X	5.0	≥ 4.0'		< 4.0'		
		Length Y	4.9	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0' * 1		< 5.0'*1		RR1 ICRR
PI	SHOP WE TELEVILLE SHOPE SOURCE SHOPE	Slope X	1.7	≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y	0.5	≤2.0%		>2.0%		
	Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	able		Pass		Fail	
4	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (n
1	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 526 Print name clearly Certifica
-	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	1.9		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





