WASHINGTON COUNTY
OREGON

ADA Curb Ramp New Construction Inspection Form (Parallel)

OREGON						
NW 309th St	24952.54		NW North	n Ave		
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West R		on.gov/odot/Engineering/Documents	
	Calibration Date 10/22/2024 (mm/dd/yy)				_RoadwayEng/ADA_ExhibitA.pdf for more corner styles. Use Washington County corner numbering system.	
R	AMP RUN 1	Pass	Fail		11, 2	
PL		1.2 ≤ 2.0% ■ >		2	Corner	
Ramp Style	Running Slope 1			Corner Position	Positions 1	
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	1.4 ≤ 2.0% ■ >	2.0%	Position 3	5 2A	
	Detectable Warning	Y Y	N	1	3	
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	ip Height	0 ≤ 1/4" ■ >	1/4"	3A	^	
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	0.6 ≤ *	>*	2	North	
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	0.6 ≤ 8.3% ■ >	8.3%>		1	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	2.8 ≤ 5.0% ■ >		1 4 12	Ramp 1	
-	Det. warning full width of ramp		N .	Ramp Position	5	
— Clear Space area is the width of Ramp Run 1	RAMP RUN 2	Pass	Fail	POSICIOII	PE Stamp (required for	
·	Running Slope 2	6.9 ≤ 8.3% ■ >	8.3%		private development)	
	ength 2	7.5				
(inlets, alianment, etc.)	Cross Slope 2	2 ≤ 2.0% ■ >	2.0%			
	RAMP RUN 3	Pass	Fail			
	Running Slope 3	5.4 ≤ 8.3% ■ >				
B Paun 3 79			0.5%			
Run 1/ Run 2	Length 3	6				
Counter stone	Cross Slope 3	1.9 ≤ 2.0% ■ >	> 2.0%	Comments:	_	
T	URN SPACE	Pass	Fail	5 in core hole in RR2. Asphalt not		
V	Width X	5.0 ≥ 4.0' ■	< 4.0'	completed.	. Asphail not	
PARALLEL RAMP (PL)	ength Y	5.55 ≥ 4.0'*1 ■ <	< 4.0'*1	completed.		
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 ■ <	< 5.0'*1			
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.4 ≤ 2.0%	> 2.0%			
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	1.2 ≤ 2.0% ■ >	> 2.0%			
Parks	MISCELLANEOUS	Pass	Fail	Inspector's Signature	Date (mm/dd/yy	
Counter Slope (5.0% max.)	Clear Width (feet)	≥ 4.0'	< 4.0'	Darrell Wyant	52638	
* If constrained at back of walk, min, Y length is 5'.	ntersection Control Type	SU Slope of Rd.		Print name clearly	Certification No	
Gutter Flow Slope (as directed)	··		1/2"	3J Consulting		
H	lorizontal Gaps	○ ≤ 1/2" ■ >	> 1/2"	Company/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





