

## **ADA Curb Ramp New Construction Inspection Form (Perpendicular)**

Nw 288 ave		24952.54				Nw SI	hadd	lon st
North-South Road Name		Project No. Shee	et No.	ntersection N	lo.	East-W	est Ro	oad Name
		Calibration Date	nan	(mm/dd,	/yy)			k - ') ' y ‡ #
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner
The passing value for Gutt depends on the Intersection	tion Control Type. At a t be ≤ Slope of the Road, at	Length 1 Cross Slope 1	10.85	≤ 2.0%		>2.0%		Position 3 Positions 2A 2
Signalized or Uncontrolled		Detectable Warning (Y,N) Lip Height		Υ		N . 1 / 4"		3A North
If Back of Ramp Obstruction is Yes, turn space ngth Y must be minimum 5.0 ft.		Gutter Flow Slope	0.5	1/4" ≤ *		>1/4"		1 A Ramp 1
<sup>2</sup> Clear Space area is the v extends 4.0 ft into the roa	vidth of Ramp Run 1 and	Curb Running Slope (avg) Counter Slope (+/-) *2	5.3	≤ 8.3% ≤ 5.0%		>8.3% > 5.0%		Ramp Position Positions
See also <u>Standard Drawings</u> to (inlets, alignment, etc.)	assess provisions not shown:	Longest distance from corner to back of curb (see dwg on BT form)	1.5	< 5.0'		≥ 5.0'		PE Stamp (requ private develop
	X X X X	Detectable warning extends full width of ramp throat opening		Y		N		
PERPENDICULAR RAMP (PR)  Pedestrian Access Route (to measure Clear Width)		TURN SPACE LANDING	G NON	JE	Pass		Fail	
		Width X	4.2	≥ 4.0'		< 4.0'		
		Length Y	6.4	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'*1		
		Slope X	1.2	≤2.0%		>2.0%		
	erde verde de different blad de die die bestellig der ein de der eine er de d De de	Slope Y	1.5	≤2.0%		>2.0%		
Cross Slope (2.0% max.)		MISCELLANEOUS Traversa	able		Pass		Fail	
Running Slope (8.3%	28.0 m	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date
Counter Slope (5.0% i		Flare Slope 2		≤ 10%		<10%	Ш	Darrell Wyant 52
Turning Space (X & Y * If constrained at bac	) (2.0% max. / 4' x 4' min.)* k of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Print name clearly Certifi
Gutter Flow Slope (as	directed)	Intersection Control Type	SY	Slope of	Road	0.4		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





