

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	7.000.27							
N	lw 291st	24952.54				Nw Ke	eenoi	n
No	rth-South Road Name	Project No. Shee	et No.	ntersection N	lo.	East-W	est Ro	ad Name
		Calibration Date		(mm/dd/	/yy)			k - ') - ' y ‡ #
	Ramp Style PR	RAMP RUN 1		≤ 8.3%	Pass	>8.3%	Fail	4 Corner
depends	ssing value for Gutter Flow Slope (GFS) Is on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Running Slope 1 Length 1		3 0.570		7 0.370		Corner Position 3 Positions 2A
		Cross Slope 1	11.3	≤ 2.0%		>2.0%		1 2 3
•	ed or Uncontrolled (SU), GFS must be ≤ and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Detectable Warning (Y,N) Lip Height	Y 0	Y 1/4"		N >1/4"		3A North
	k of Ramp Obstruction is Yes, turn space	Gutter Flow Slope	12	1/4 ≤ *		>1/4 >*		
length Y must be minimum 5.0 ft. ² Clear Space area is the width of Ramp Run 1 and		Curb Running Slope (avg) Counter Slope (+/-) *2	1.24	≤ 8.3%		>8.3%		Ramp Positions
	4.0 ft into the roadway. Standard Drawings to assess provisions not shown:		3.0	≤ 5.0%		> 5.0%	ᆜ	Position PE Stamp (require
	alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		private developm
Aun i de		Detectable warning extends full width of ramp throat opening	Υ	Y		N		
		TURN SPACE LANDING	G NO	NE	Pass		Fail	
		Width X	pass	≥ 4.0'		< 4.0'		
		Length Y	pass	≥ 4.0'*1		< 4.0'*1		Comments: RR1 ICRR
		Back of Ramp Obstruction (Y/N)	Υ	≥ 5.0'*1		< 5.0'*1		THE POINT
PI	PERPENDICULAR RAMP (PR) Pedestrian Access Route (to measure Clear Width)	Slope X		≤2.0%		>2.0%		
	Detectable Warning Surface	Slope Y		≤2.0%		>2.0%		
	Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	ble		Pass		Fail	
4	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (m
\mathcal{I}	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	4.1	≥ 4.0'		< 4.0'		Print name clearly 5263 Certifica
-	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	0.8		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





