

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

OKEGON			<u> </u>				•
NW 309th Ave	24952.54				NW Y	orksl	hire St
North-South Road Name	Project No. Shee	et No. Int	ersection N	0.	East-W	est Ro	oad Name
	Calibration Date	11/15/202	(mm/dd,	/yy)			k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR	RAMP RUN 1		10.20/	Pass	> 0 20/	Fail	3 Corner
	Running Slope 1	8.1	≤ 8.3%		>8.3%	Ш	Corner Positions
The passing value for Gutter Flow Slope (GFS)	Length 1	5.0					Position 3 2A
depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1	2.3	≤ 2.0%		>2.0%		
Signalized or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)	Υ	Υ		N		3A -
5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.	Lip Height	0	1/4"		>1/4"		North
¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Gutter Flow Slope	A 1.7	<u>≤</u> *		>*		
	Curb Running Slope (avg)	0.6	≤ 8.3%		>8.3%		1 Ramp 1 Positions
² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Counter Slope (+/-) *2	5.2	≤ 5.0%		> 5.0%		Position 5
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (required private developme
X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening	Υ	Υ		N		
	TURN SPACE LANDING	G NONE		Pass		Fail	
Pan 1 // * ***	Width X	5.1	≥ 4.0'		< 4.0'		
Gurjer Flow storm			> 4 0!*1		4 01 4 1		Comments:
Counter slope Slope	Length Y	7	≥ 4.0'*1		< 4.0'*1	Ш	RR1 exceeds ADA due to craftsmansh
	Back of Ramp Obstruction (Y/N)	Υ	≥ 5.0′*1		< 5.0'*1		
PERPENDICULAR RAMP (PR)	Slope X		≤2.0%		>2.0%		
Pedestrian Access Route (to measure Clear Width)	Slope Y	2.3	≤2.0%		>2.0%		
Detectable Warning Surface	MISCELLANEOUS Traversa	ble		Pass		Fail	
← Cross Slope (2.0% max.) ← Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mm/
Hunning Slope (8.3% max.) Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%	H	
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	5.1	≥ 4.0'		< 4.0'	\exists	Darrell Wyant 52638
in constrained at back of wark, min. I length is 5.	Intersection Control Type	SU	Slope of	Boad.	1.4		Print name clearly Certification
Gutter Flow Slope (as directed)	Horizontal Gaps		≤1/2"	Noau			3J Consulting
	ποπεοπται σαμό		21/2		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





