

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

Nw Kaye	24952.54				Nw SI	naddo	on
North-South Road Name	Project No. She	et No. Int	tersection N	lo.	East-W	est Ro	ad Name
	Calibration Date	7/30/2024	(mm/dd,	/yy)			k - ') - ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner Corner
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Length 1 Cross Slope 1 Detectable Warning (Y,N) Lip Height	10.7 Y	≤ 2.0% Y 1/4"		>2.0% N >1/4"		Positions Positions Positions North
length Y must be minimum 5.0 ft.	Gutter Flow Slope Curb Running Slope (avg)	0 1.0 2.22	≤ * ≤ 8.3%		>1/4 >* >8.3%		1 Ramp Positions
² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway. See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Counter Slope (+/-) *2 Longest distance from corner to back of curb	4.5	≤ 5.0% < 5.0'		> 5.0% ≥ 5.0'		Position PE Stamp (requiprivate develop
Aun 1 / Au	(see dwg on BT form) Detectable warning extends full width of ramp throat opening		Υ		N		
	TURN SPACE LANDIN Width X	IG NONI	E ≥ 4.0'	Pass	< 4.0'	Fail	
Counter slope Courter slope	Length Y	1.7	≥ 4.0'*1		< 4.0'*1		Comments:
PERPENDICULAR RAMP (PR)	Back of Ramp Obstruction (Y/N) Slope X	Y	≥ 5.0'*1 ≤2.0%		< 5.0'*1 >2.0%		
Pedestrian Access Route (to measure Clear Width) Detectable Warning Surface	Slope Y		≤2.0%		>2.0%		
Cross Slope (2.0% max.)	MISCELLANEOUS Traversal Flare Slope 1	able	≤ 10%	Pass	< 10%	Fail	Inspector's Signature Date
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Flare Slope 2 Clear Width (feet)		≤ 10% ≥ 4.0'		<10% < 4.0'		Darrell Wyant 52 Print name clearly Certifit
Gutter Flow Slope (as directed)	Intersection Control Type Horizontal Gaps	SY	Slope of ≤1/2"	Road	0.7 > 1/2"		3J Consulting Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





