WASHINGTON COUNTY OREGON ADA	Curb Ramp New Constr	uction Inspection Form (Par	allel)
311th	24952.54	Claxter	
North-South Road Name	Project No. Sheet No.	Intersection No. East-West	Road Name See https://www.oregon.gov/odot/Engineering/Documents
	Calibration Date	9/20/2024 (mm/dd/yy)	_RoadwayEng/ADA_ExhibitA.pdf for more corner styles Use Washington County corner numbering system.
PL	RAMP RUN 1	Pass Fail	3 2
Ramp Style	Running Slope 1	≤ 2.0%  > 2.0%	Corner Positions Positions
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	≤ 2.0%  > 2.0%	Position 3
depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the	Detectable Warning	Y N	
Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" > 1/4"	3A -
must be $\leq$ 5.0%, and at Stop or Yield (SY), GFS must be $\leq$ 2.0%.	Gutter Flow Slope	2.5 ≤ * > *	2 North
	Curb Running Slope(avg)	6.58 ≤ 8.3% ■ > 8.3%>	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	5.4 ≤ 5.0%  ■ >  5.0%	1 Ramp Positions
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp	Y Y N	Position
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass Fail	PE Stamp (required for
	Running Slope 2	≤ 8.3%  > 8.3%	private development)
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Length 2	9.25	
(mets, ungiment, etc.)	Cross Slope 2	3.6 ≤ 2.0%   > 2.0%	
Counter slope  Sign 3  Sign 2  Guiter Now slope	RAMP RUN 3	Pass Fail	
	Running Slope 3	≤ 8.3%  > 8.3%	
	Length 3	7.3	
	Cross Slope 3	3.3 ≤ 2.0% > 2.0%	Comments:
	TURN SPACE	Pass Fail	
	Width X	4.85 ≥ 4.0' < 4.0'	IITD, gt2. BOR drop off.
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 <b>■</b> < 4.0'*1	
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 < 5.0'*1	
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0%	

Slope Y (Running Slope 1)

**MISCELLANEOUS** 

Clear Width (feet)

**Horizontal Gaps** 

Intersection Control Type

Detectable Warning Surface

Cross Slope (2.0% max.)

Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)\*
\* If constrained at back of walk, min. Y length is 5'.

4.85

SY

≤ 2.0%

≥ 4.0'

> 2.0%

< 4.0'

Pass

Slope of Rd. 2.5

≤ 1/2" ■ > 1/2"

Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting

Date (mm/dd/yy)

Certification No.

52638



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





