

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

OREGON	•	•		•	•	•
NW 288 ter	24952.54			NW m	ays s	t
North-South Road Name	Project No. Shee	et No. Intersection	n No.	East-We	est Roa	nd Name
	Calibration Date	8/13/2024 (mm,	/dd/yy)			k - ') · · · · · · · · · · · · · · · · ·
Ramp Style PR	RAMP RUN 1		Pass		Fail	3 Corner
nump style TTX	Running Slope 1	≤ 8.39	%	>8.3%	Ш	Corner
The passing value for Gutter Flow Slope (GFS)	Length 1	12.5				Position 3
epends on the Intersection Control Type. At a 1idblock (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1	≤ 2.09	%	>2.0%		1 2 3
ignalized or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)	Y		N		3A
.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.	Lip Height	1/4"		>1/4"		North
If Back of Ramp Obstruction is Yes, turn space ength Y must be minimum 5.0 ft.	Gutter Flow Slope	/A 1.2 ≤ *		>*		
	Curb Running Slope (avg)	3.2 ≤ 8.39	%	>8.3%		1 Ramp Positions
² Clear Space area is the width of Ramp Run 1 and xtends 4.0 ft into the roadway.	Counter Slope (+/-) *2	2.7 ≤ 5.0%	6	> 5.0%		Position 5
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	< 5.	0'	≥ 5.0'		PE Stamp (requi private develop
X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening	Y		N		
/* * * / * / * / * / * / * / * / * / *	TURN SPACE LANDIN	IG NONE	Pass		Fail	
## ## Aun 1 ## ## ## ## ## ## ## ## ## ## ## ## #	Width X	5.35 ≥ 4.0)' =	< 4.0'		
Counter singe						Comments:
Counter slope Slope	Length Y	4.8 ≥ 4.0'*		< 4.0'*1	Ш	IITD RR1 ICRR standing ramp
	Back of Ramp Obstruction (Y/N)	≥ 5.0'*	:1	< 5.0' * 1		
PERPENDICULAR RAMP (PR)	Slope X	≤2.0%	ó 🔲	>2.0%		
Pedestrian Access Route (to measure Clear Width)	Slope Y	≤2.0%	6	>2.0%		
Detectable Warning Surface	MISCELLANEOUS Traversa		Pass		Fail	
Cross Slope (2.0% max.)	Flare Slope 1	≤ 109		< 10%	一.	Inspector's Signature Date (
Running Slope (8.3% max.) Counter Slope (5.0% max.)	Flare Slope 2	≤ 109	\equiv	<10%		-
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	≥ 4.0		< 4.0'	1 1115	Darrell Wyant 526
in constrained at back of wark, min. Theright is 5.	Intersection Control Type			0.1	l l	Print name clearly Certific
Gutter Flow Slope (as directed)	Horizontal Gaps	≤1/2				3J Consulting
	Horizontal Gaps	≥1/2		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





