

## **ADA Curb Ramp New Construction Inspection Form (Perpendicular)**

NW 209th	24952.54			Nw Ki	King
North-South Road Name	Project No. Shee	et No. Inter	section No.	East-W	Vest Road Name
	Calibration Date		(mm/dd/yy)		k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR	RAMP RUN 1	_	Pas	_	Fail
	Running Slope 1	8.6	≤ 8.3%	>8.3%	Corner Position 3
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a	Length 1		_	7	5 2
Midblock (MB), GFS must be $\leq$ Slope of the Road, at	Cross Slope 1	4.95	≤ 2.0%	>2.0%	1 3
Signalized or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)	Υ	Υ	N	3A -
5.0%, and at Stop or Yield (SY), GFS must be $\leq$ 2.0%.	Lip Height	0	1/4"	>1/4"	North 2
<sup>1</sup> If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Gutter Flow Slope	0.8	≤ *	>*	
	Curb Running Slope (avg)	8.52	≤ 8.3%	>8.3%	Ramp Positions
<sup>2</sup> Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Counter Slope (+/-) *2	1.0	≤ 5.0%	> 5.0%	
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'	] ≥ 5.0'	PE Stamp (requ private develop
A Pun i A A A A A A A A A A A A A A A A A A	Detectable warning extends full width of ramp throat opening	Υ	Υ	N	
	TURN SPACE LANDING	G NONE	Pas	S	Fail
	Width X		≥ 4.0'	< 4.0'	
Counter slope Gutjer Flow slope	Length Y	fail ≥	4.0'*1	< 4.0'*1	Comments:
1000e*6500082**(5):0	Back of Ramp Obstruction (Y/N)	Y ≥	: 5.0'*1 <b>=</b>	< 5.0'*1	1 🔲
PERPENDICULAR RAMP (PR)	Slope X		≤2.0%	>2.0%	
Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%	>2.0%	
Detectable Warning Surface	MISCELLANEOUS Traversa		Pas	1	Fail
← Cross Slope (2.0% max.) ← Running Slope (8.3% max.)	Flare Slope 1		≤ 10%	< 10%	Inspector's Signature Date
Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%	<10%	
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*  * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	4.95	≥ 4.0'	< 4.0'	Darrell Wyant Print name clearly  Certifi
Gutter Flow Slope (as directed)	Intersection Control Type	SU S	Slope of Roa	o.9	3J Consulting
	Horizontal Gaps		≤1/2"	> 1/2"	Company/Agency



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





