

## **ADA Curb Ramp New Construction Inspection Form (Perpendicular)**

K	lw 289th	24952.54				Nw ur	nion	
	orth-South Road Name		et No. In	tersection N	lo.			pad Name
		Calibration Date $8/13/2024$ (mm/dd/yy) $k = -\frac{1}{2}$						
		RAMP RUN 1	0, 10, 202		Pass		Fail	,
	Ramp Style PR	Running Slope 1		≤ 8.3%		>8.3%		Corner Positions
-	sing value for Gutter Flow Slope (GFS)	Length 1	4.5					Position 3
•	Is on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1		≤ 2.0%		>2.0%		3
Signalize	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Υ		N		(3A)
5.0%, an	d at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height		1/4"		>1/4"		2 North
	of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope	2 A	≤ *		>*		
		Curb Running Slope (avg)	1.08	≤ 8.3%		>8.3%		1 Ramp Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	5.5	≤ 5.0%		> 5.0%		Position 5
	o <u>Standard Drawings</u> to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	0.55	< 5.0'		≥ 5.0'		PE Stamp (require private developme
1	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Υ		N		
Pun 1		TURN SPACE LANDING	G NON	E	Pass		Fail	
		Width X	5.0	≥ 4.0'		< 4.0'		
		Length Y	5.2	≥ 4.0'*¹		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'*1		IITD, RR 1 fail
PI	ERPENDICULAR RAMP (PR)	Slope X	2.3	≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%	$\Box$	
	Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail	
<b>4</b>	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mr
<b>A</b>	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	5.0	≥ 4.0'		< 4.0'	$\Box$	Darrell Wyant 52638 Print name clearly Certificat
TO	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road			·
	and the state of the state of	Horizontal Gaps		≤1/2"		> 1/2"		3J Consulting Company/Agency
		<u> </u>		-		,	-	··· ··/// 'O-···o/



ADA Curb Ramp Images
Attached photos must be in .pdf format in order to be placed





