WASHINGTON COUNT			
OREGO			
Nw Glencoe rd			

ADA Curb Ramp New Construction Inspection Form (Parallel)

Nw Glencoe rd.	24952.54	Nw p	acific st.		
North-South Road Name	Project No. Sheet	No. Intersection No. East-W	Vest Road Name	See https://www.oregon.gov/odot/Engineering/Documents	
	Calibration Da	te 10/9/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more corner styles Use Washington County corner numbering system.	
PL	RAMP RUN 1		Fail 4] 2	
Ramp Style	Running Slope 1	1.7 ≤ 2.0%	Corner	Corner Positions	
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	1.7 ≤ 2.0% ■ > 2.0%	Position	3 5 2A	
depends on the Intersection Control Type. At a	Detectable Warning	Y N		1	
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" ■ > 1/4"		3A -	
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	1.2 ≤ * ■ > *		North 2	
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	1.6 ≤ 8.3% ■ > 8.3%>			_
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	2.8 ≤ 5.0% ■ > 5.0%	1	Ramp 1 Positions	_
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ra	amp Y N	Ramp Position	5	
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass	Fail	PE Stamp (required for	
	Running Slope 2	7.9 ≤ 8.3% ■ > 8.3%		private development)	
See also Standard Drawings to assess provisions not shown:	Length 2	11.5			
(inlets, alignment, etc.)	Cross Slope 2	2.5 ≤ 2.0% > 2.0%			
Committee and the committee an	RAMP RUN 3	Pass	Fail		
18 Run 3 1839	Running Slope 3	4.3 ≤ 8.3% ■ > 8.3%			
To Run 2 1	Length 3	5.5			
Guiller Fix	Cross Slope 3	1.6 ≤ 2.0% ■ > 2.0%	Company		
Counter slope	TURN SPACE	Pass	Fail	S.	\neg
	Width X	5.0 ≥ 4.0' ■ < 4.0'			
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 ■ < 4.0'*1			
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 < 5.0'*1			
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.7 ≤ 2.0% > 2.0%			
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	1.7 ≤ 2.0% > 2.0%			Ī
Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail Inspector's S	ignature Date (mm/dd	/yy)
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4" x 4" min.)*	Clear Width (feet)	5.0 ≥ 4.0' < 4.0'	Darrell V	Wyant 52638.	0
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SY Slope of Rd. 0.3	Print name c		No
Gutter Flow Slope (as directed)			3J Consultir	ng	
	Horizontal Gaps	No ≤ 1/2" > 1/2"	Company/Ag	gency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





