WASHINGTON COUNTY
OREGON

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

	Nw. Glencoe rd.	24952.54	Nw	pacific st.	
	North-South Road Name	Project No. Sheet No.	Intersection No. East-	West Road Name See https://www.oregon.gov/odot/Engineering/Documents	
Calibration Date  Calibration					
	PL	RAMP RUN 1 Running Slope 1	Pass  1.3 ≤ 2.0% ■ > 2.0%	Fail 3 Corner Position 2	
depe Midb Road must or Yie *1 If I space *2 Cla and e	nds on the Intersection Control Type. At a block (MB), GFS must be ≤ Slope of the , at Signalized or Uncontrolled (SU), GFS be ≤ 5.0%, and at Stop eld (SY), GFS must be ≤ 2.0%.  Back of Ramp Obstruction is Yes, turn e length Y must be minimum 5.0 ft.  ear Space area is the width of Ramp Run 1 extends 4.0 ft into the roadway.	Cross Slope 1  Detectable Warning  Lip Height  Gutter Flow Slope  Curb Running Slope(avg)  Counter Slope (+/-)*2  Det. warning full width of ramp  RAMP RUN 2  Running Slope 2	Pass  7.4 ≤ 8.3% ■ > 8.3%	3 A North	
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)  PARALLEL RAMP (PL)  PARALLEL RAMP (PL)		Length 2 Cross Slope 2 RAMP RUN 3	8.3 1.2 ≤ 2.0% ■ > 2.0% Pass	Fail	
		Running Slope 3 Length 3 Cross Slope 3 TURN SPACE Width X	$5.6$ $\leq 8.3\%$ $\Rightarrow 8.3\%$ $10.4$ $1.4$ $\leq 2.0\%$ $\Rightarrow 2.0\%$ Pass $6.95$ $\geq 4.0'$ $\Rightarrow < 4.0'$	Comments:  IITD, cut domes in center of ramp.	
		Length Y  Back of Ramp Obstruction (Y/N)	$\geq 4.0^{1*1}$ $\leq 4.0^{1*1}$ $\leq 4.0^{1*1}$ $\leq 5.0^{1*1}$		
\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	Detectable Warning Surface	Slope X (Cross Slope 1) Slope Y (Running Slope 1)	2.5 ≤ 2.0%  > 2.0% 1.3 ≤ 2.0%  > 2.0%		
	Hunning Stope (8.3% max.)  Counter Slope (5.0% max.)  Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*  *If constrained at back of walk, min. Y length is 5'.	MISCELLANEOUS  Clear Width (feet)  Intersection Control Type	Pass $ \begin{array}{c c} \hline                                    $	Fail Inspector's Signature Date (mm/dd/yy  Darrell Wyant 52638.0  Print name clearly Certification No.  3J Consulting	
	- 1	Horizontal Gaps	No ≤ 1/2" > 1/2"	Company/Agency	



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





