

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

S.M.S.S.M.	<u>-</u>	_	-	=	
Nw 291 st	23885.56		Nw k	ing ave	
North-South Road Name	Project No. Sheet	No. Intersection N	o. East-V	Vest Road	I Name
	Calibration Date 07	7/23/24 (mm/dd/	/yy)		k - ') - '
Ramp Style PR	RAMP RUN 1 Running Slope 1	≤ 8.3%	Pass >8.3%	Fail	Corner
the passing value for Gutter Flow Slope (GFS) epends on the Intersection Control Type. At a lidblock (MB), GFS must be ≤ Slope of the Road, at	Length 1	14.2 ≤ 2.0%	>2.0%		Corner Positions Positions 2/
gnalized or Uncontrolled (SU), GFS must be \leq 3.09e of the Road, at 9.00 gnalized or Uncontrolled (SU), GFS must be \leq 2.0%.	Detectable Warning (Y,N)	Y	■ N		3A North
If Back of Ramp Obstruction is Yes, turn space ngth Y must be minimum 5.0 ft.	Lip Height Gutter Flow Slope N/A	1/4" 1.5 ≤ *	>1/4"		4 Ramp 1
Clear Space area is the width of Ramp Run 1 and tends 4.0 ft into the roadway.	Curb Running Slope (avg) Counter Slope (+/-) *2	3.56 ≤ 8.3% 5 ≤ 5.0%	>8.3% > 5.0%		Ramp Position
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	< 5.0'	≥ 5.0'		PE Stamp (requ private develop
X-3	Detectable warning extends full width of ramp throat opening	Y	N		
	TURN SPACE LANDING	NONE	Pass	Fail	
	Width X	≥ 4.0'	< 4.0'		Common and a
Counter slope Guiffer Flow slope	Length Y	≥ 4.0'*1	< 4.0'*	¹	Comments: Rr1 icrr tool joints in turn space
DEDDENDIOU AD DAMO (DD)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1	< 5.0'*		•
PERPENDICULAR RAMP (PR) Pedestrian Access Route (to measure Clear Width)	Slope X	≤2.0%	>2.0%		
Detectable Warning Surface	Slope Y	≤2.0%	>2.0%		
Cross Slope (2.0% max.)	MISCELLANEOUS Traversal	ole ≤ 10%	Pass < 10%	Fail	nspector's Signature Date
Running Slope (8.3% max.) Counter Slope (5.0% max.)	Flare Slope 2	≤ 10% ≤ 10%	<10%		
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	≥ 4.0'	< 4.0'		Darrell Wyant 526 Print name clearly Certifi
Gutter Flow Slope (as directed)	Intersection Control Type	Slope of		3	BJ Consulting
	Horizontal Gaps	≤1/2"	> 1/2"	С	Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





