WASHINGTON COUNT			
OREGO			
NIM Timorio			

ADA Curb Ramp New Construction Inspection Form (Parallel)

NW Timeric	24952.54	NW	North Ave		
North-South Road Name	Project No. Sheet No	. Intersection No. East	-West Road Name	See https://www.oregon.gov/odot/Engineering/I	
	Calibration Date	10/22/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more co Use Washington County corner numbering	
PL F	RAMP RUN 1	Pass	Fail 4		2
	Running Slope 1	7.4 ≤ 2.0% > 2.0%	Corner	Corner Positions	
The passing value for dutter flow slope (drs)	Cross Slope 1	0.8 ≤ 2.0% ■ > 2.0%	Position	3 5 2A	1
	Detectable Warning	Y Y N		3	
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	ip Height	0 ≤ 1/4" ■ > 1/4"		3A -	
	Gutter Flow Slope	1.1 ≤ * ■ > *		2 North	
	Curb Running Slope(avg)	8.65 ≤ 8.3% > 8.3%	. 🔳		
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	<u>2.4</u> ≤ 5.0% > 5.0%	1 Ramp	Ramp 1 Positions	
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ram	p N Y N	Position	5	
	RAMP RUN 2	Pass	Fail	PE Stamp (requi	ired for
F	Running Slope 2	≤ 8.3% > 8.3%		private develop	ment)
See also <u>Standard Drawings</u> to assess provisions not shown: [(inlets, alignment, etc.)	ength 2	5.8	_		
(iniets, diignment, etc.)	Cross Slope 2	^{7.2} ≤ 2.0% > 2.0%			
F	RAMP RUN 3	Pass	Fail		
	Running Slope 3	≤ 8.3% > 8.3%			
Brun 3	ength 3	5.8			
fun 2	Cross Slope 3	7.6 ≤ 2.0% > 2.0%			
Counter slope Gutter Tlow slope	TURN SPACE	Pass	Fail	:s:	
		3.85 ≥ 4.0' < 4.0'			
	Width X		.=1		
PARALLEL RAMP (PL)	∟ength Y				
TAUALLE I MAII (I L)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 < 5.0'*1			
Ammond	Slope X (Cross Slope 1)	0.8 ≤ 2.0% > 2.0%			
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	7.4 ≤ 2.0% > 2.0%			
	MISCELLANEOUS	Pass	Fail Inspector's S	Signature Dat	e (mm/dd/yy
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	≥ 4.0' < 4.0'	Darrell \		2638.0
* if constrained at back of walk, min. Y length is 5°.	ntersection Control Type	SY Slope of Rd. 3.2	Print name of	clearly Cert	ification No
Gutter Flow Slope (as directed)	Horizontal Gaps	○ ≤ 1/2" ■ > 1/2"	3J Consulti		
<u>'</u>	10112011ta1 0ap3	/2 - / 1/2	Company/A	gency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





