North-South Road Name	24952.54	Co	mmercial	
	Project No. Sheet No Calibration Date	eus	t-West Road Name	See https://www.oregon.gov/odot/Engineering/Docu _RoadwayEng/ADA_ExhibitA.pdf for more corner Use Washington County corner numbering syste
PL	RAMP RUN 1	Pass	Fail 3	
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Running Slope 1	≤ 2.0% > 2.0%	Corner	Corner Positions
	Cross Slope 1	pe 1 ≤ 2.0% > 2.0%	Position	Position 3
	Detectable Warning	Y N		2
	Lip Height	0 ≤ 1/4" ■ > 1/4"		3A 3
nust be \leq 5.0%, and at Stop	Gutter Flow Slope	6.2 ≤ * > *		2 North
r Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	1.82 ≤ 8.3% ■ > 8.3%	> 🔲	
^I If Back of Ramp Obstruction is Yes, turn pace length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	8.4 ≤ 5.0% ■ > 5.0%	6 1 Ramp	Ramp 1 Positions
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Det. warning full width of ram		Position	5
	RAMP RUN 2	Pass	Fail	PE Stamp (require
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Running Slope 2	≤ 8.3% > 8.3%	. 🔳 📗	private developme
	Length 2	7.15		
	Cross Slope 2	≤ 2.0% > 2.0%	· [_]	
Counter slope Series Tion Slope Counter slope	RAMP RUN 3	Pass	Fail	
	Running Slope 3	≤ 8.3% > 8.3%	6	
	Length 3	7.2		
	Cross Slope 3	2.4 ≤ 2.0% = > 2.0%		
	TURN SPACE	Pass	Fail	
	Width X	5.15 ≥ 4.0' ■ < 4.0'	IITD gt2	<u>)</u>
	The state of the s		.1 []	
PARALLEL RAMP (PL)	Length Y	7.25 ≥ 4.0'*1 ■ < 4.0'*	' -	
PARALLEL RAMP (PL) PARALLEL RAMP (PL)	Length Y Back of Ramp Obstruction (Y/N)	$^{7.25}$ $\geq 4.0^{1*1}$ $< 4.0^{1*}$ $< 5.0^{1*1}$ $< 5.0^{1*}$		
372 %			1	

MISCELLANEOUS

Clear Width (feet)

Horizontal Gaps

Intersection Control Type

Cross Slope (2.0% max.)

Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

5.15

SY

Pass

Slope of Rd. 7.1

< 4.0'

> 1/2"

≥ 4.0'

≤ 1/2"

Date (mm/dd/yy)

52638

Certification No.


Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





