	WASHINGTON COUNT				
	OREGO	o			
-		7			

ADA Curb Ramp New Construction Inspection Form (Parallel)

	NW Curtis	23885.56		NW Paci	fic	
	North-South Road Name	Project No. Sheet No.	Intersection No.	East-West		gon.gov/odot/Engineering/Documents
		Calibration Date	7/10/2024 (mm/dd/yy)		_ , -	DA_ExhibitA.pdf for more corner styles. n County corner numbering system.
PL Ramp Style		RAMP RUN 1	Pass ≤ 2.0% ■ > 2	Fail		Corner 2
		Running Slope 1			Corner Position 3	Positions 2A
*The passing value for Gutter Flow Slope (GFS)		Cross Slope 1	1.7 ≤ 2.0% > 2	2.0%		5 2
depends on the Intersection Control Type. At a Midblock (MB), GFS must be \leq Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.		Detectable Warning	N Y	N	1	3
		Lip Height	≤ 1/4" ■ > 1	1/4"	3A -	1
		Gutter Flow Slope	0.7 ≤ *	*	2	North
		Curb Running Slope(avg)	7.18 ≤ 8.3% ■ > 8	8.3%>		1
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		Counter Slope (+/-)*2	^{5.5} ≤ 5.0% ■ >	5.0%	2	Positions
* ² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		Det. warning full width of ramp	Y Y	N	Ramp Position	5
		RAMP RUN 2	Pass	Fail		PE Stamp (required for
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		Running Slope 2	5 ≤ 8.3%	8.3%		private development)
		Length 2	7.6			
		Cross Slope 2	2.3 ≤ 2.0% > 3	2.0% ■		
		RAMP RUN 3	Pass	Fail	.]	
		Running Slope 3	5.6 ≤ 8.3% ■ >	8.3%		
3	of Run 3	Length 3	7.7			
Guller		Cross Slope 3	1.6 ≤ 2.0% ■ >	2.0%	Comments:	
Co	ounter slope	TURN SPACE	Pass	Fail		
		Width X	5.0 ≥ 4.0' ■ <	4.0'	midblock east side	
PARALLEL RAMP (PL)		Length Y	5.0 ≥ 4.0'*1 ■ <	4.0'*1		
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 <	5.0'*1		
[Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.7 ≤ 2.0% ■ >	2.0%		
→		Slope Y (Running Slope 1)	1.7 ≤ 2.0% ■ >	2.0%		
		MISCELLANEOUS	Pass	Fail	Inspector's Signature	Date (mm/dd/yy
	Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	5.0 ≥ 4.0' <	4.0'	Darrell Wyant	52638
	* If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SU Slope of Rd.	1.0	Print name clearly	Certification N
	Gutter Flow Slope (as directed)	Horizontal Gaps		1/2"	3J Consulting	
		Totazontai Gaps	- 1/2	-,-	Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





