WASHINGTON COUNTY OREGON AE	OA Curb Ramp New Cons	struction Inspection	on Form (Con	nbination)	
Nw 287	24952.54		Nw mays		
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West Road N	ame o:	-)
	Calibration Date	8/20/2024 (mm/dd,	/yy)	k - °) ° - U ‡ #	
Ramp Style C	RAMP RUN 1	Pas	s Fail		
* The passing value for Gutter Flow Slope (GFS) depends on the Intersection Condition Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be 2.0%. * ¹If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 feet. * ² Clear Space area is the width of Ramp Run 1 and extends 4.0' into the roadway.	Running Slope 1 Length 1 Cross Slope 1 Detectable Warning (Y/N) Lip Height Gutter Flow Slope Curb Running Slope (avg) N/A	3.9 ≤ 8.3% ■ 4.9 1.1 ≤ 2.0% ■ Y ■ ≤ 1/4" ■ 0.9 ≤ * 8.73999999999999999999999999999999999999	> 2.0% N > 1/4" > * > *8.3%	3A 1 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Corner Positions 2A 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Counter Slope (+/-)*2	3.6 ≤ 5.0%	> 5.0%	Position	5
Pass Fail	RAMP RUN 2	Pass			PE Stamp (required fo
Longest distance from detectable warning corner to back of curb (to nearest inch) $< 5.0'$ $\geq 5.0'$	Running Slope 2 Length 2 Cross Slope 2	7.6 ≤ 8.3% ■ 4.45 1.1 ≤ 2.0% ■	> 2.0%		private development)
Detectable warning extends full width of ramp throat opening	RAMP RUN 3 Running Slope 3 Length 3 Cross Slope 3	Pas: 4.2 ≤ 8.3% ■ 4.5 ■ 1.4 ≤ 2.0% ■	> 8.3%		
Flore Slope Run 3 Run 2 Run 1	TURN SPACE Width X	Pas 6.15 ≥ 4.0'	< 4.0'	Comments:	
Counter slope Combination RAMP (C)	Length Y Back of Ramp Obstruction (Y/N	4.95 ≥4.0'*1 ■ 1) ≥5.0'*1	< 4.0'*1		
COMBINATION RAMP (C)	Slope X Slope Y	2.5 ≤2.0% ≤2.0% ≤2.0%	> 2.0% = > 2.0%		
Pedestrian Access Route (to measure Clear Width) Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.)	MISCELLANEOUS Traversab Flare Slope 1 Flare Slope 2		> 10%	Inspector's Signature	Date (mm/do
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'. Gutter Flow Slope (as directed)	Clear Width (feet) Horizontal Gaps (Y/N)	4.95 ≥ 4.0' ≤ 1/2" ■	< 4.0'	Darrell Wyant Print name clearly 3J Consulting	52638 Certification
	Intersection Control Type	Slope of Ro	ad 1.3	Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





