

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	200020									
N	lw 288 ave	24952.54				Nw Sh		naddon st		
No	rth-South Road Name	Project No. Shee	et No.	ntersection N	o.	East-W	est Ro	oad Name		
		Calibration Date	nan	(mm/dd/	/yy)			k - ')' - ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '		
	Ramp Style PR	RAMP RUN 1	_	1	Pass		Fail	4 Corner		
		Running Slope 1	7.8	≤ 8.3%		>8.3%	Ш	Corner Positions		
•	ssing value for Gutter Flow Slope (GFS) s on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Length 1	5.0					Position 3		
•		Cross Slope 1	1.5	≤ 2.0%		>2.0%				
Signalized or Uncontrolled (SU), GFS must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.		Detectable Warning (Y,N)		Y		N		3A		
		Lip Height		1/4"		>1/4"		North		
	of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope	0.8	≤ *		>*				
		Curb Running Slope (avg)	3.44	≤ 8.3%		>8.3%		1 Ramp Positions		
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	2.4	≤ 5.0%		> 5.0%		Position		
	Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (required private developme		
Counter slope		Detectable warning extends full width of ramp throat opening		Y		N				
		TURN SPACE LANDIN	G NON	JE	Pass		Fail			
		Width X	5.0	≥ 4.0'		< 4.0'				
		Length Y	5.0	≥ 4.0'*1		< 4.0'*1		Comments:		
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'*1				
Р	ERPENDICULAR RAMP (PR)	Slope X		≤2.0%		>2.0%				
	Pedestrian Access Route (to measure Clear Width)	Slope Y	2.1	≤2.0%		>2.0%				
	Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail			
+	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mm,		
A	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%				
T	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 5263 Print name clearly Certificati		
	Gutter Flow Slope (as directed)	Intersection Control Type	MB	Slope of	Road					
	Called 1 on Giope (as directed)	Horizontal Gaps		≤1/2"		> 1/2"		3J Consulting Company/Agency		
				/-		- 1/2		Company/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





