WASHIN	HINGTON COUNTY OREGON						
NW T	imeric						
North-So	uth Road Name						

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

	NW Timeric		23885.56					NW Lenu	IX				
North-South Road Name			Project No.	She	et No.	Intersection No.		East-West	Road Name		egon.gov/odot/Engine		
Calibration Date  7/16/2024 (mm/dd/yy) RoadwayEng/ADA_ExhibitA.pdf for more corner Use Washington County corner numbering syste													
PL Ramp Style			P RUN 1			Pa	ass	Fail	3			2	
			ing Slope 1			≤ 2.0%	> 2	.0%	Corner	_ []	Corner Positions	1	
*The	passing value for Gutter Flow Slope (GFS)	Cross	Slope 1			≤ 2.0%	> 2	.0%	Position	3	5	2A	
depends on the Intersection Control Type. At a			Detectable Warning Y N							1		3	
	lock (MB), GFS must be ≤ Slope of the , at Signalized or Uncontrolled (SU), GFS	Lip Height ≤ 1/4" ■ > 1/4"						3A 1					
must be ≤ 5.0%, and at Stop			Gutter Flow Slope						North 2				
	eld (SY), GFS must be ≤ 2.0%.	Curb	Running Slope(av	/g)		1.5 ≤ 8.3%	> 8	.3%> 🔳					
* <sup>1</sup> If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.			nter Slope (+/-)*2		11	.3 ≤ 5.0%	>	5.0%	1 Dame	12	Ramp 1 Positions		
* <sup>2</sup> Clo	ear Space area is the width of Ramp Run 1	Det. v	warning full width	n of	ramp	Y		N	Ramp Position		5		
and e	xtends 4.0 ft into the roadway.	RAMI	P RUN 2			Pa	ass	Fail		PE Stamp (req			
		Runn	ing Slope 2		L	≤ 8.3%	> 8	.3%			private dev	relopment)	
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)			th 2		7	.15							
			Slope 2		7.3	≤ 2.0%	> 2	.0%					
15 Page 3 1830		RAM	P RUN 3			Pa	ass	Fail					
		Runn	ing Slope 3			≤ 8.3%	> 8	3.3%					
OF	Constitution of the Consti	Lengt	th 3		6	.9							
Counter stope Gutter How stope		Cross	Cross Slope 3 7.1 ≤ 2.0% > 2.0% ■				2.0%	Commont					
		TURN SPACE			Pass Fail			Comments:					
		Widt	h X		3.			4.0'	NID Fa 	NTD Fails RR 1 and Turn space			
PARALLEL RAMP (PL)			th Y		4.	≥ 4.0'*1	<b>■</b> < 4	.0'*1					
	PARALLEL RAMP (PL)	Back c	of Ramp Obstruction	(Y/I	N)	≥ 5.0'*1	< 5	5.0'*1					
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)   ≤ 2.0%   > 2.0%											
	Cross Slope (2.0% max.)  Running Slope (8.3% max.)  Counter Slope (5.0% max.)	Slope	e Y (Running Slope 1)			≤ 2.0%	> 2	2.0%					
		MISC	ELLANEOUS			Pa	ass	Fail	Inspector's	Signature		Date (mm/dd/yy	
		Clear	· Width (feet)		3.5	≥ 4.0'	≥ 4.0'   Darrell Wyant				52638		
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*  * If constrained at back of walk, min. Y length is 5'.		, ,	16	١	SU Slope of Rd. 1.0					Certification No		
	Gutter Flow Slope (as directed)		Intersection Control Type						3J Consult	ing			
		Horiz	Horizontal Gaps			○ ≤ 1/2"			Company/A	gency			



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





