	WASHINGTON COUNTY
	OREGON

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

	Nw 314th ave.	24952.54		Nw. Cot	tage st	
	North-South Road Name	Project No. Sheet No.	Intersection No.	East-West I		gon.gov/odot/Engineering/Documents
		Calibration Date	10/12/2024 (mm/dd/yy)			DA_ExhibitA.pdf for more corner styles. n County corner numbering system.
PL		AMP RUN 1	Pass	Fail	2	2
		unning Slope 1		2.0%	Corner Position	Corner Positions
*The passing value for Gutter Flow Slope (GFS)		ross Slope 1	1.4 ≤ 2.0%  > 2	2.0%	Position 3	5 2A
depends on the Intersection Control Type. At a		etectable Warning	N Y	N 🔳		3
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS		p Height	0.5 ≤ 1/4" > 1	_/4"	3A -	1
must be ≤ 5.0%, and at Stop		outter Flow Slope	0.7 ≤ * ■ >	*	2	North
or Yield (SY), GFS must be ≤ 2.0%.		Curb Running Slope(avg)	2.34 ≤ 8.3% ■ > 8	3.3%>		11
<ul> <li>*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.</li> <li>*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.</li> </ul>		ounter Slope (+/-)*2	10.5 ≤ 5.0%  <b>■</b> >		1 4	Ramp 1 Positions
		et. warning full width of ramp		N 🔳	Ramp Position	5
		AMP RUN 2	Pass	Fail	Tosicion	PE Stamp (required for
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)		unning Slope 2	12.6 ≤ 8.3% > 8	3.3%		private development)
		ength 2				
		ross Slope 2	≤ 2.0% > 2	2.0%		
		AMP RUN 3	Pass	Fail		
		unning Slope 3	13.4 ≤ 8.3% > 8	8.3%		
T	15 Run 3	ength 3				
Counter slope  Counter slope  PARALLEL RAMP (PL)		ross Slope 3	≤ 2.0%  > 2	2.0%	Comments	
		URN SPACE	Pass	Fail	Comments:	
		Vidth X	4.5 ≥ 4.0'	4.0'	No dome,no RR2,no	RR3
		ength Y	5.0 ≥ 4.0'*1 ■ < 4	1.0'*1		
	PARALLEL RAMP (PL)	ack of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 < 5	5.0'*1		
		lope X (Cross Slope 1)	1.4 ≤ 2.0% > 2	2.0%		
-	Detectable Warning Surface  Cross Slope (2.0% max.)	lope Y (Running Slope 1)	9.4 < 2.0% > 2	2.0%		
		MISCELLANEOUS	Pass	Fail	Inspector's Signature	Date (mm/dd/yy
₹ *\bar{\pi}	Counter Slope (5.0% max.)  Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	lear Width (feet)	4.5 ≥ 4.0' <	4.0'	Darrell Wyant	52638.0
	In constrained at back of walk, film. The light is 5.	itersection Control Type	SU Slope of Rd. 0	).7	Print name clearly	Certification No
Gutter Flow Slope (as directed)		orizontal Gaps		1/2"	3J Consulting	
		·			Company/Agency	



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





