WASHINGTON COUNTY OREGON ADA	Curb Ramp New Constr	uction Inspection Form (Para	allel)		
Main	24952.54	Hillcrest			
North-South Road Name	Project No. Sheet No.	Intersection No. East-West	Road Name See https://www.oregon.gov/odot/Engineering/Documents		
Calibration Date Calibration					
PL	RAMP RUN 1	Pass Fail	3 2		
Ramp Style	Running Slope 1	≤ 2.0% > 2.0%	Corner Positions		
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	5.9 ≤ 2.0% > 2.0% ■	Position 3 Positions 2A		
depends on the Intersection Control Type. At a	Detectable Warning	Y M			
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" ■ > 1/4"	3A 1		
must be \leq 5.0%, and at Stop	Gutter Flow Slope	4.5 ≤ * > *	2 North		
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	6.64 ≤ 8.3% ■ > 8.3%>			
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	8.3 ≤ 5.0% ■ > 5.0%	Ramp Positions		
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp		Position		
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass Fail	PE Stamp (required for		
	Running Slope 2	≤ 8.3% > 8.3%	private development)		
See also Standard Drawings to assess provisions not shown:	Length 2	7.8			
(inlets, alignment, etc.)	Cross Slope 2	≤ 2.0% > 2.0%			
Is Run 3 Base 1 Run 2	RAMP RUN 3	Pass Fail			
	Running Slope 3	12.5 ≤ 8.3% > 8.3%			
	Length 3				
2 Pun 2 8/7)	Cross Slope 3	≤ 2.0% > 2.0%			
Counter slope Surfer flow slope	TURN SPACE	Pass Fail	Comments:		
	Width X	5.0 ≥ 4.0¹ ■ < 4.0¹	IITD gt2. R3 asphalt		
PARALLEL RAMP (PL)	Length Y	6.1 ≥ 4.0'*1 ■ < 4.0'*1			
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 < 5.0'*1			
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	5.9 ≤ 2.0% > 2.0% ■			

Detectable Warning Surface

Cross Slope (2.0% max.)

Running Slope (8.3% max.)

Counter Slope (5.0% max.)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

Inspector's Signature	Date (mm/dd/y
D 11.147 4	E0000

Darrell Wyant	52638
Print name clearly	Certification No

3J Consulting

Slope Y (Running Slope 1)

MISCELLANEOUS

Clear Width (feet)

Horizontal Gaps

Intersection Control Type

5.0

SY

≤ 2.0%

≥ 4.0'

≤ 1/2"

> 2.0%

< 4.0'

> 1/2"

Pass

Slope of Rd. 4.3

Fail



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





