WASHINGTON COU				
OREGO	o			
	_			

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

	C. I. C.					
	Nw 314th ave	24952.54		Nw. Com	nmercial st.	
1	North-South Road Name	Project No. Sheet No.	o. Intersection No.	East-West F	Road Name See https://www.oregon.gov/odot/Engineer	ring/Documents
		Calibration Date	10/9/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for mo Use Washington County corner numb	
		RAMP RUN 1	Pass	Fail		16.2
PL				2.0%	Corner	2
		Running Slope 1			Corner Positions Positions	1
*The passing value for Gutter Flow Slope (GFS)		Cross Slope 1	6.9	2.0%	3 5	ZA
		Detectable Warning	Y	N		
Midblock (MB), GFS must be ≤ Slope of the		ip Height	1.0 ≤ 1/4" > 2	1/4"	1	5
indud, at signalized of official office (50), dis					3A North	
or Yield (SY), GFS must be ≤ 2.0%.		Gutter Flow Slope	7.3	> *		2
		Curb Running Slope(avg)	9 ≤ 8.3% > 8	8.3%>	1	
* <sup>1</sup> If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		Counter Slope (+/-)*2	5.1 ≤ 5.0%  >	5.0%	1 Ramp 1 Positions	1
* <sup>2</sup> Clear Space area is the width of Ramp Run 1		Det. warning full width of ram	p Y Y	N	Ramp Position	
		RAMP RUN 2	Pass	Fail	PE Stamp (ro	equired for
		Running Slope 2	≤ 8.3% > 3	8.3%	private deve	elopment)
(inlets alianment etc.)		ength 2				
		Cross Slope 2	≤ 2.0%  > 2	2.0%		
		RAMP RUN 3	Pass	Fail		
		Running Slope 3	≤ 8.3% >	8.3%		
=	pl Pun 3	ength 3				
Counter slope Gutter Now slope TI		Cross Slope 3	≤ 2.0% >	2.0%		
		URN SPACE	Pass	Fail	Comments:	
				4.0'	No dome,no RR2,no RR3	
		Width X				
		ength Y		4.0'*1		
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 ■ <	5.0'*1		
		Slope X (Cross Slope 1)	6.9 ≤ 2.0% ■ >	2.0%		
< !		Slope Y (Running Slope 1)	15.2 ≤ 2.0% ■ >	2.0%		
	Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail	Inspector's Signature	Date (mm/dd/y
	Counter Slope (5.0% max.)	Clear Width (feet)	3.5 ≥ 4.0' <	4.0'	Darrell Wyant	52638.0
	* If constrained at back of walk, min. Y length is 5'.	ntersection Control Type		7.3		Certification N
Gutter Flow Slope (as directed)		•		1/2"	3J Consulting	
		Horizontal Gaps	> 1/2	1/2	Company/Agency	



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





