

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

- Control										
Nw 289 ave		24952.54	Nw Ke			eno	enon st			
North-South Road Name		Project No. Sheet No. Intersection No. East-West				est Ro	oad Name		`	
		Calibration Date	8/6/2024	(mm/dd/	/yy)			k - ') y ‡ #		
	Ramp Style PR	RAMP RUN 1		-	Pass		Fail	1	Corner	
		Running Slope 1	4.6	≤ 8.3%		>8.3%	Ш	Corner	neitions (1
The passing value for Gutter I		Length 1	10.0					Position 3	5	A
epends on the Intersection C Iidblock (MB), GFS must be ≤	, · ·	Cross Slope 1	1.7	≤ 2.0%		>2.0%			,	3
gnalized or Uncontrolled (SU), GFS must be ≤ 0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.		Detectable Warning (Y,N)		Υ		N		3A -	1	
		Lip Height		1/4"		>1/4"		2	North	2
If Back of Ramp Obstruction ngth Y must be minimum 5.0		Gutter Flow Slope	/A 2	≤ *		>*				
		Curb Running Slope (avg)	1.16	≤ 8.3%		>8.3%			Ramp 1 Cositions	
Clear Space area is the widt xtends 4.0 ft into the roadwa	'	Counter Slope (+/-) *2	5	≤ 5.0%		> 5.0%		Ramp Position	5	
See also <u>Standard Drawings</u> to asse (inlets, alignment, etc.)	ss provisions not shown:	Longest distance from corner to back of curb (see dwg on BT form)	1.7	< 5.0'		≥ 5.0'			PE Stamp (private dev	
XI XI	17	Detectable warning extends full width of ramp throat opening		Y		N				
/* ** * // \$ //	1	TURN SPACE LANDIN	IG NON	NE	Pass		Fail			
Aun 1	***	Width X	3.2	≥ 4.0'		< 4.0'				
Counter slope Counter slope	ope of	Length Y	6.9	≥ 4.0'*1		< 4.0'*1		Comments:		
		Back of Ramp Obstruction (Y/N)		≥ 5.0' * 1		< 5.0'*1				
PERPENDICULAR RAMP (PR)		Slope X	4.6	≤2.0%		>2.0%				
Pedestrian Access Route (Notice for the Associated and the Control of the Associated Control of	Slope Y	1.7	≤2.0%		>2.0%				
			able		Pass		Fail			$\overline{}$
Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)		Flare Slope 1		≤ 10%		< 10%		Inspector's Signature		Date
		Flare Slope 2		≤ 10%		<10%				_
Turning Space (X & Y) (2.0 * If constrained at back of v)% max. / 4' x 4' min.)*	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant Print name clearly		526 Certifi
Gutter Flow Slope (as direct	- 175 ATE	Intersection Control Type		Slope of	Road	1.5				
	7,407.74 6	Horizontal Gaps		· ≤1/2"		> 1/2"		3J Consulting Company/Agency		
		· · · · · · · · · · · · · · · · · · ·						6		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





