WASHINGTON COUNTY
OREGON

ADA Curb Ramp New Construction Inspection Form (Parallel)

NW 309th St		24952.54 NW North Ave						
N	orth-South Road Name	Project No. Sheet No.	Intersection No.	East-\	West Roa		pregon.gov/odot/Engine	
		Calibration Date	10/22/2024 (mm	n/dd/yy)			/ADA_ExhibitA.pdf for m gton County corner num	
	PL	RAMP RUN 1			Fail	4	0	2
Ramp Style		Running Slope 1	2.2 ≤ 2.0%	> 2.0%		Corner	Corner Positions	1
*The passing value for Gutter Flow Slope (GFS)		Cross Slope 1	≤ 2.0%	> 2.0%		Position 3	5	2A
depends on the Intersection Control Type. At a		Detectable Warning	Y	■ N		1	-	3
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS		Lip Height	0 ≤ 1/4"	> 1/4"		3A	1	*
must be ≤ 5.0%, and at Stop		Gutter Flow Slope	1.4 ≤ *	■ >*		2	North	2
or Yield (SY), GFS must be ≤ 2.0%.		Curb Running Slope(avg)	4.97 ≤ 8.3%	8.3% >			(F
* ¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		Counter Slope (+/-)*2	3.6 ≤ 5.0%	 > 5.0%		1 4	Ramp 1	
* ² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		Det. warning full width of ramp	YY	■ N		Ramp Position	5	
		RAMP RUN 2		Pass	Fail		PE Stamp (required for
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		Running Slope 2	6.1 ≤ 8.3%	> 8.3%			private dev	
		Length 2	10.9					
		Cross Slope 2	1.6 ≤ 2.0%	> 2.0%				
CQ25	E SEA THE AND	RAMP RUN 3		Pass	Fail			
Counter slope PARALLEL RAMP (PL)		Running Slope 3	4.4 ≤ 8.3%	> 8.3%				
		Length 3	4.9					
		Cross Slope 3	2 ≤ 2.0%	2 .0%		`a na na na na na		
		TURN SPACE		Pass	Fail	Comments:		
		Width X	8.1 ≥ 4.0¹	■ <4.0'				
		Length Y	7.35 ≥ 4.0'*1	< 4.0'*1				
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1	< 5.0'*1				
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0%	> 2.0%				
	Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	2.2 ≤ 2.0%	> 2.0%				
	← Running Slope (8.3% max.)	MISCELLANEOUS		Pass	Fail	nspector's Signature		Date (mm/dd/yy
	Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	≥ 4.0'	< 4.0'		Darrell Wyant		52638
₩.	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SU Slope o	of Rd. 1.6		Print name clearly		Certification N
	Gutter Flow Slope (as directed)	Horizontal Gaps	o ≤ 1/2"	> 1/2"		3J Consulting		
		TIOTIZOTICAL GAPS	2 1/2			`omnany/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





