	WASHINGTON COUNTY	1			
	OREGON				
	NW Timeric				
	North-South Road Name				
		PL			
		Ramp Sty			
dep Mid Roa mus	*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be \leq Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.				
* ¹ l [.] spa	f Back of Ramp Obstruction is Ye ce length Y must be minimum 5.0	s, turn) ft.			
* ² (and	Clear Space area is the width of R extends 4.0 ft into the roadway.	amp Run 1			

(inlets, alignment, etc.)

ADA Curb Ramp New Construction Inspection Form (Parallel)

23885.56

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Ramp Style

	Project No. Sheet No.	Intersection No.	East-	West F	Road Name	See https://www.oreg		eering/Documents more corner styles.
	Calibration Date	(mm/d	ld/yy)			_ ,	n County corner nui	•
	RAMP RUN 1	Pa	ass	Fail		1		2
	Running Slope 1	≤ 2.0%	> 2.0%		Corner		Corner Positions	1 XX
	Cross Slope 1	≤ 2.0%	> 2.0%		Position	3	5	2A
	Detectable Warning	Y	N		=	1		3
	Lip Height	≤ 1/4"	> 1/4"		(3A	\uparrow	
	Gutter Flow Slope	0.5 ≤ *	>*		ì	2	North	2
	Curb Running Slope(avg)	9.92 ≤ 8.3%	> 8.3%>		=	4		1
	Counter Slope (+/-)*2	0.8 ≤ 5.0%	> 5.0%			2	Ramp 1]	
	Det. warning full width of ramp	Y	N		Ramp Position		5	
	RAMP RUN 2	Pa	ass	Fail			PE Stamp	(required for
	Running Slope 2	≤ 8.3%	> 8.3%					evelopment)
	Length 2	6						
	Cross Slope 2	3.9 ≤ 2.0%	> 2.0%					
RAMP RUN 3		Pass		Fail				
	Running Slope 3	≤ 8.3%	> 8.3%					
	Length 3	7.95						
	Cross Slope 3	3.3 ≤ 2.0%	> 2.0%					
	TURN SPACE	Pa	Pass		Comments:			
	Width X	3.45 ≥ 4.0'	< 4.0'		NTD Fail	RR 1 And T	S	
	Length Y	5.0 ≥ 4.0'*1 [■ < 4.0'* ¹					
	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1	< 5.0'* ¹					
	Slope X (Cross Slope 1)	≤ 2.0%	> 2.0%					
	Slope Y (Running Slope 1)	≤ 2.0%	> 2.0%					
	MISCELLANEOUS	Pa	ass	Fail	Inspector's Si	gnature		Date (mm/dd/yy
	Clear Width (feet)	3.45 ≥ 4.0'	< 4.0'		Darrell V	•		52638
Intersection Control Type		Slope of Rd. 0.5			Print name cl			Certification N
	Horizontal Gaps	o ≤ 1/2" [> 1/2"		3J Consultin	-		
	I .		_		COMPANY/AR	CIICY		

NW Belgium

Reset Entire Form

Keep Intersection, Reset Fields



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





