WASHINGTON COUNTY OREGON ADA	Curb Ramp New Constr	uction Inspection Form (Par	allel)
CALGON	23885.56		
North-South Road Name	Project No. Sheet No.	Intersection No. East-West	Road Name See https://www.oregon.gov/odot/Engineering/Documents
	Calibration Date		_RoadwayEng/ADA_ExhibitA.pdf for more corner styles. Use Washington County corner numbering system.
PL	RAMP RUN 1	Pass Fail	4
Ramp Style	Running Slope 1	≤ 2.0% > 2.0%	Corner
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	≤ 2.0% > 2.0%	Position 3 Positions 2A
depends on the Intersection Control Type. At a	Detectable Warning	Y ■ N	200
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	≤ 1/4" ■ > 1/4"	3A North
must be $\leq$ 5.0%, and at Stop or Yield (SY), GFS must be $\leq$ 2.0%.	Gutter Flow Slope	1.7 ≤ * ■ > *	2 North
	Curb Running Slope(avg)	<b>4.58</b> ≤ 8.3% ■ > 8.3%>	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	3.9 ≤ 5.0%  ■ >  5.0%	1 Ramp Positions
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp		Position 5
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass Fail	PE Stamp (required for
	Running Slope 2	5.6 ≤ 8.3% ■ > 8.3%	private development)
See also Standard Drawings to assess provisions not shown:	Length 2	7.1	
(inlets, alignment, etc.)	Cross Slope 2	0.8 ≤ 2.0% ■ > 2.0%	
COMMENT AND CO. STATE OF THE CO.	RAMP RUN 3	Pass Fail	
E Run 3 Trans	Running Slope 3	9.2 ≤ 8.3% > 8.3%	
1 May 177	Length 3	7.5	
Run 2	Cross Slope 3	≤ 2.0%  > 2.0%	
Counter slope	TURN SPACE	Pass Fail	Comments:
	Width X	5.0 ≥ 4.0' <b>■</b> < 4.0'	DWS IITD Fails turn space, RR to nowhere
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 <b>■</b> < 4.0'*1	
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1  < 5.0'*1	
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0%	
Detectable Warning Surface  Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	≤ 2.0%  > 2.0%	

Running Slope (8.3% max.) Counter Slope (5.0% max.)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)\*
\* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

DWS IITD Fails turn space,	RR	to
nowhoro		

Inspector's Signature	Date (mm/dd/y
Darrell Wyant	52638
Print name clearly	Certification N
3J Consulting	

**MISCELLANEOUS** 

Clear Width (feet)

**Horizontal Gaps** 

Intersection Control Type

5.0

SU

Pass

Slope of Rd. 0.3

≤ 1/2" ■ > 1/2"

< 4.0'

≥ 4.0'

Fail

Company/Agency



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





