

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

-	20027			-		_	_	
N	lw 292	24952.54				Nw w	est u	nion
No	orth-South Road Name	Project No. Shee	et No.	Intersection N	lo.	East-W	est Ro	oad Name
		Calibration Date	3/6/2024	(mm/dd,	/yy)			k - ') - '
	Ramp Style PR	RAMP RUN 1	5.0	≤ 8.3%	Pass	>8.3%	Fail	Corner
	sing value for Gutter Flow Slope (GFS)	Running Slope 1 Length 1	8.35]				Corner Position 3 Positions 2A
•	s on the Intersection Control Type. At a k (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1		≤ 2.0%		>2.0%		1 2 3
	ed or Uncontrolled (SU), GFS must be ≤ and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Detectable Warning (Y,N) Lip Height		Υ		N		3A North
f Bacl	of Ramp Obstruction is Yes, turn space	Gutter Flow Slope	2.1	1/4" ≤ *		>1/4" >*		2
	Y must be minimum 5.0 ft. Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Curb Running Slope (avg)	3.98	≤ 8.3%		>8.3%		Ramp Positions
		Counter Slope (+/-) *2	2.6	≤ 5.0%		> 5.0%		Position DE Stamp (requi
	o Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	0.6	< 5.0'		≥ 5.0'		private develop
/.	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Y		N		
/=	****	TURN SPACE LANDING	G NO	NE	Pass		Fail	
	Pun 1	Width X	4.7	≥ 4.0'		< 4.0'		
ounter	slope Gurijer Flow slope	Length Y	5.6	≥ 4.0'*1		< 4.0'*1		Comments: IITD not full width rr1 icrr
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*1		< 5.0'*1		
P	Pedestrian Access Route (to measure Clear Width)	Slope X	10.8	≤2.0%		>2.0%		
	Detectable Warning Surface	Slope Y		≤2.0%		>2.0%		
	Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	able		Pass		Fail	
←	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date
1	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Darrell Wyant 526
Ţ	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Print name clearly Certifi
•	Gutter Flow Slope (as directed)	Intersection Control Type		Slope of	Road	2.1		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





