	WASHINGTON COUNTY				
	OREGON				
	Nw 289th pl				
	North-South Road Name				
		PL			
		Ramp Sty			
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be $\leq$ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be $\leq$ 5.0%, and at Stop or Yield (SY), GFS must be $\leq$ 2.0%.					
* <sup>1</sup> l <sup>.</sup> spa	f Back of Ramp Obstruction is Yece length Y must be minimum 5.	es, turn 0 ft.			
* <sup>2</sup> ( and	Clear Space area is the width of F extends 4.0 ft into the roadway	Ramp Run 1			

(inlets, alignment, etc.)

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

24952.54

Ramp Style


	Project No. Sheet No.	Intersection No.	East-	-West F	Road Name		egon.gov/odot/Engine	
	Calibration Date	8/30/2024 (mm	n/dd/yy)				DA_ExhibitA.pdf for mon County corner num	
Π	RAMP RUN 1		Pass	Fail	2	1 111	77.0	2
	Running Slope 1	1.3 ≤ 2.0%	> 2.0%		Corner		Corner Positions	1
	Cross Slope 1	1.4 ≤ 2.0%	> 2.0%		Position _	3	5 2	2A
	Detectable Warning	Y	■ N		_	1		3
	Lip Height	≤ 1/4"	> 1/4"		(	3A	<u> </u>	
	Gutter Flow Slope	1.2 < *	> *		<u> </u>	2	North	2
	Curb Running Slope(avg)	1.74 ≤ 8.3%	> 8.3%>			4	Ramp 1	1
	Counter Slope (+/-)*2	2 ≤ 5.0%	>  5.0%	I 🗌	1	12	Positions	1
	Det. warning full width of ramp	Y	N		Ramp Position		5	
	RAMP RUN 2		Pass	Fail			PE Stamp (	required for
	Running Slope 2	8.3% ≤ 8.3%	> 8.3%					velopment)
	Length 2	7.3						
	Cross Slope 2	1.5 ≤ 2.0%	<b>=</b> > 2.0%					
	RAMP RUN 3		Pass	Fail				
	Running Slope 3	5.4 ≤ 8.3%	> 8.3%					
	Length 3	4.75						
	Cross Slope 3	0.7 ≤ 2.0%	> 2.0%		Comments			
	TURN SPACE		Pass	Fail	Comments	) <b>.</b>		
	Width X	5.1 ≥ 4.0'	<b>■</b> < 4.0'					
	Length Y	5.15 ≥ 4.0'*1	< 4.0'*1					
	Back of Ramp Obstruction (Y/N)	≥ 5.0'*¹	< 5.0'*1					
	Slope X (Cross Slope 1)	1.3 ≤ 2.0%	> 2.0%					
	Slope Y (Running Slope 1)	1.4 ≤ 2.0%	> 2.0%					
	MISCELLANEOUS		Pass	Fail	Inspector's Si	gnature		Date (mm/dd/y
	Clear Width (feet)	≥ 4.0'	< 4.0'		Darrell V			52638
	Intersection Control Type	SY Slope o	of Rd. 1.2	]	Print name cl			Certification N
	Horizontal Gaps	≤ 1/2"	> 1/2"		3J Consultin			
	i '				Company/Ag	ency		

Nw west union rd

PARALLEL RAMP (PL)

PARALLEL RAMP (PL)

See also Standard Drawings to assess provisions not shown:



Turning Space (X & Y) (2.0% max. / 4' x 4' min.)\*
\* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





