

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

Nw Kaye	24952.54				NW K	ing	
North-South Road Name	Project No. Shee	et No. In	tersection N	о.	East-W	est Ro	pad Name
	Calibration Date		(mm/dd/	/ yy)			k -) - y ‡ #
Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner Corner
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be \leq Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.	Length 1 Cross Slope 1	10.9	≤ 2.0%		>2.0%		Position 3 Positions 2A 3
	Detectable Warning (Y,N) Lip Height	Y	Y 1/4"		N >1/4"		3A North
¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Gutter Flow Slope Curb Running Slope (avg)	0 0.4 5.08	≤ * ≤ 8.3%		>* >8.3%		4 Ramp 1
² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Counter Slope (+/-) *2	2.3	≤8.3% ≤ 5.0%		> 5.0%		Ramp Position PE Stamp (require
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		private developm
Aun 1 Au Mar	Detectable warning extends full width of ramp throat opening		Υ		N		
	TURN SPACE LANDING Width X	G NON	E ≥ 4.0'	Pass	< 4.0'	Fail	
Counter slope Guiter Flow slope	Length Y	3.3	≥ 4.0'*1		< 4.0'*1		Comments: RR1 ICRR, IITD
PERPENDICULAR RAMP (PR)	Back of Ramp Obstruction (Y/N) Slope X	Y	≥ 5.0'*1 ≤2.0%		< 5.0'*1 >2.0%		
Pedestrian Access Route (to measure Clear Width) Detectable Warning Surface	Slope Y		≤2.0%		>2.0%		
☐ Cross Slope (2.0% max.) ☐ Running Slope (8.3% max.)	MISCELLANEOUS Traversa Flare Slope 1	able	≤ 10%	Pass	< 10%	Fail	Inspector's Signature Date (mi
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Flare Slope 2		≤ 10% ≥ 4.0'		<10%		Darrell Wyant 5263
* If constrained at back of walk, min. Y length is 5'. Gutter Flow Slope (as directed)	Clear Width (feet) Intersection Control Type	CII	Slope of	Road	< 4.0'		Print name clearly Certifica 3J Consulting
unical contraction of the delayer of the delayer of the properties (1000/2000 €	Horizontal Gaps	SU	≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





