

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

Nw Kaye	24952.54				Nw SI	haddo	on
North-South Road Name	Project No. Shee	et No. Int	ersection N	o.	East-W	est Roa	ad Name
	Calibration Date	7/30/2024	(mm/dd/	/yy)			k - ')' - ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	1 Corner Positions
he passing value for Gutter Flow Slope (GFS) epends on the Intersection Control Type. At a lidblock (MB), GFS must be ≤ Slope of the Road, at gnalized or Uncontrolled (SU), GFS must be ≤	Length 1 Cross Slope 1 Detectable Warning (Y,N)	10.9	≤ 2.0% Y		>2.0% N		Position 3 Positions 2A 2 2A 3
5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%. ¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Lip Height Gutter Flow Slope	0 0.5	1/4" ≤ *] >1/4"] >*		North
2 Clear Space area is the width of Damp Dun 1 and	Curb Running Slope (avg) Counter Slope (+/-) *2	5.2 3.7	≤ 8.3% ≤ 5.0%		>8.3% > 5.0%		Ramp Position Positions
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (requi private develop
Au Maria Mar	Detectable warning extends full width of ramp throat opening		Υ		N		
	TURN SPACE LANDING Width X	G NONE	E ≥ 4.0'	Pass	< 4.0'	Fail	
Counter slope Gurjer Flow slope	Length Y	1.9	≥ 4.0'*1		< 4.0'*1		Comments:
PERPENDICULAR RAMP (PR)	Back of Ramp Obstruction (Y/N) Slope X	Υ	≥ 5.0'*1 ≤2.0%		< 5.0'*1 >2.0%		
Pedestrian Access Route (to measure Clear Width) Detectable Warning Surface	Slope Y		≤2.0%		>2.0%		
Cross Slope (2.0% max.)	MISCELLANEOUS Traversa Flare Slope 1	able	≤ 10%	Pass	< 10%	Fail	Inspector's Signature Date
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Flare Slope 2 Clear Width (feet)	4.1	≤ 10% ≥ 4.0'		<10% < 4.0'		Darrell Wyant Print name clearly Certific
Gutter Flow Slope (as directed)	Intersection Control Type Horizontal Gaps	SU	Slope of ≤1/2"	Road	0.6 > 1/2"		3J Consulting Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





