WASHINGTON COUNT			
OREGO			
Ny Clanges rd			

ADA Curb Ramp New Construction Inspection Form (Parallel)

Nw. Glencoe rd	24952.54		Nw. Pacif	fic st.		
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West R		regon.gov/odot/Enginee	
	Calibration Date	10/9/2024 (mm/dd/yy)			ADA_ExhibitA.pdf for motor ton County corner numb	
PL RA	AMP RUN 1	Pass	Fail	2		2
	unning Slope 1	1.5 ≤ 2.0% ■ > 2	.0%	Corner	Corner Positions	1 The
*The passing value for Gutter Flow Slope (GFS)	oss Slope 1	1.8 ≤ 2.0% ■ > 2	.0%	Position 3	5	2A 1
depends on the Intersection Control Type. At a De	etectable Warning	Y Y	N		2	3
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	p Height	0 ≤ 1/4" ■ > 1	/4"	3A -	\uparrow	
	utter Flow Slope	1.5 ≤ * ■ >	*	2	North	2
	urb Running Slope(avg)	4.04 ≤ 8.3% ■ > 8	.3%>		(1	F
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	ounter Slope (+/-)*2	<u>1.4</u> ≤ 5.0% ■ > !	5.0%	1	Ramp 1 I	
-	• • •		N	Ramp Position	5	
"- Clear Space area is the width of Ramp Run 1	AMP RUN 2	Pass	Fail	TOSITION	PE Stamp (r	equired for
Ru	unning Slope 2	3.4 ≤ 8.3% ■ > 8	.3%		private deve	
	ength 2	7.8				
(inlets, alignment, etc.)	ross Slope 2	1.3 ≤ 2.0% ■ > 2	.0%			
R/	AMP RUN 3	Pass	Fail			
y Ru	unning Slope 3	9.3	3.3%			
Le Run 3	ength 3	14.25				
Guttar	ross Slope 3	≤ 2.0% > 2	2.0%			
Counter slope TU	JRN SPACE	Pass	Fail	Comments:		
w	/idth X	5.0 ≥ 4.0' ■ < 4	4.0'			
PARALLEL RAMP (PL)	ength Y	5.0 ≥ 4.0'*1 ■ < 4	.0'*1			
PARALLEL RAMP (PL)	ack of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 ■ < 5	5.0'*1			
Pedestrian Access Route (to measure Clear Width)	ope X (Cross Slope 1)	1.8 ≤ 2.0% > 2	2.0%			
Detectable Warning Surface Cross Slope (2.0% max.)	ope Y (Running Slope 1)	1.5 ≤ 2.0% ■ > 2	2.0%			
Running Slope (8.3% max.)	IISCELLANEOUS	Pass	Fail	Inspector's Signature		Date (mm/dd/yy
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	ear Width (feet)	5.0 ≥ 4.0' < 4	4.0'	Darrell Wyant		52638.0
* If constrained at back of walk, min. Y length is 5'.	tersection Control Type	SU Slope of Rd. 2	.6	Print name clearly		Certification N
Gutter Flow Slope (as directed)	orizontal Gaps		L/2"	3J Consulting		
l i i			,-	Company/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





