

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

Nv	v 287 ave	24952.54				Nw S	hadd	on st
Nort	h-South Road Name	Project No. Shee	et No. I	ntersection N	lo.	East-W	est Ro	oad Name
		Calibration Date	nan	(mm/dd,	/yy)			k - ')' - ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner
depends o	ssing value for Gutter Flow Slope (GFS) Is on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at ed or Uncontrolled (SU), GFS must be ≤ nd at Stop or Yield (SY), GFS must be ≤ 2.0%. ck of Ramp Obstruction is Yes, turn space	Length 1 Cross Slope 1	10.1	≤ 2.0%		>2.0%		Position 3 Positions 2A
Signalized or		Detectable Warning (Y,N)		Y		N		3A North
¹ If Back o		Lip Height Gutter Flow Slope	2.8	1/4" ≤ *		>1/4" >*		North 2
² Clear Sp	nust be minimum 5.0 ft. Pace area is the width of Ramp Run 1 and .0 ft into the roadway.	Curb Running Slope (avg) Counter Slope (+/-) *2	3.58	≤ 8.3% ≤ 5.0%		>8.3% > 5.0%	>8.3% Ramp	Ramp
See also <u>S</u>	standard Drawings to assess provisions not shown: ignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	0.8	< 5.0'		≥ 5.0'		PE Stamp (requir private developn
A Conjer Flow Slope Counter slope		Detectable warning extends full width of ramp throat opening		Y		N		
		TURN SPACE LANDING	G NO	NE	Pass		Fail	
		Width X	4.0	≥ 4.0'		< 4.0'		
		Length Y	6.5	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'* ¹	Ш	
	RPENDICULAR RAMP (PR) Pedestrian Access Route (to measure Clear Width)	Slope X	0.7	≤2.0%		>2.0%		
	Detectable Warning Surface	Slope Y	1.6	≤2.0%		>2.0%		
•••••	Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	ble		Pass		Fail	
	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (r
_	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%	Ш	Darrell Wyant 526
T	Furning Space (X & Y) (2.0% max. / 4' x 4' min.)* If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Print name clearly Certific
- (Gutter Flow Slope (as directed)	Intersection Control Type	SU	Slope of	Road	0.3		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





