WASHINGTON COUNT	Г
OREGO	10

ADA Curb Ramp New Construction Inspection Form (Parallel)

	Nw. Glencoe rd	24952.54		Nw. Paci	ific st.	
	North-South Road Name	Project No. Sheet No.	Intersection No.	East-West	Road Name See https://www.oregon.gov/odot/Engineering/Documer	
		Calibration Date	10/9/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more corner styl Use Washington County corner numbering system.	es.
	PL F	RAMP RUN 1	Pass	Fail	1	2
Ramp Style		Running Slope 1	1.3 ≤ 2.0% ■ >	2.0%	Corner Position Positions	>
*The passing value for Gutter Flow Slope (GFS)		Cross Slope 1	1.2 ≤ 2.0% ■ >	2.0%	Position 3	
depends on the Intersection Control Type. At a		Detectable Warning	Y	N		
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS		ip Height	0 ≤ 1/4" ■ >	1/4"	3A 1	
must be \leq 5.0%, and at Stop		Gutter Flow Slope	1.4 ≤ *	> *	North	
or Yield (SY), GFS must be $\leq 2.0\%$.		Curb Running Slope(avg)		8.3%>		_
* ¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.					1 Ramp 1	
		Counter Slope (+/-)*2	=[5.0%]		Ramp	
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		Det. warning full width of ramp	Pass	NFail	Position	—
		Running Slope 2		8.3%	PE Stamp (required for private development)	•
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		Length 2	6.75	0.570		
		Cross Slope 2		2.0%		
		RAMP RUN 3	Pass	Fail		
		Running Slope 3	7.3 ≤ 8.3% ■ >	8.3%		
¥	15 Faun 3	Length 3	8.75			
Counter slope PARALLEL RAMP (PL)		Cross Slope 3	1.7 ≤ 2.0% ■ >	2.0%		
		TURN SPACE	Pass	Fail	Comments:	_
		Width X	5.0 ≥ 4.0'	4.0'	IITD, large comm. box in RR2	
		Length Y	5.0 ≥ 4.0 ^{1*1} ■ <	4.0'*1		
	352 2	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 - <	5.0'*1		
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.2 ≤ 2.0% ■ >	2.0%		
**************************************		Slope Y (Running Slope 1)	1.3 ≤ 2.0% ■ >			=
	1-02	MISCELLANEOUS	Pass	Fail	Inspector's Signature Date (mm/c	/v/bb
	Counter Slope (5.0% max.)	Clear Width (feet)	5.0 ≥ 4.0' <	4.0'	Darrell Wyant 52638	3.0
	* If constrained at back of walk, min, Y length is 5'.	ntersection Control Type		0.9	Print name clearly Certification	
	Gutter Flow Slope (as directed)	Horizontal Gaps		1/2"	3J Consulting	
		10.12011tai Gapa	= 1/2		Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





