

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

		0.4050.54				1		
_	lw main st	24952.54 Show	at No.	lm#======*! *!	-	Nw Yo		
No	rth-South Road Name	Project No. Shee	et No.	Intersection N	o.	East-W	est Ko	oad Name
		Calibration Date	2024-10-29	(mm/dd/	/yy) 			y ‡ #
	Ramp Style PR	RAMP RUN 1			Pass		Fail	2 Corner
		Running Slope 1	7.2	≤ 8.3%		>8.3%	Ш	Corner
	sing value for Gutter Flow Slope (GFS)	Length 1	8.45					Position 3
	ds on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1	2.0	≤ 2.0%		>2.0%		3
Signalize	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)	Υ	Υ		N		3A -
5.0%, an	d at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height	0	1/4"		>1/4"		North
	of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope	2.3	≤ *		>*		
		Curb Running Slope (avg)	3.86	≤ 8.3%		>8.3%		1 Ramp Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	5.4	≤ 5.0%		> 5.0%		Position
	o <u>Standard Drawings</u> to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (requir private developn
/	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening	Υ	Y		N		
4	4 1 1 1 1	TURN SPACE LANDING	G NOI	NE	Pass		Fail	
Counter slope Run 1 R		Width X	6.05	≥ 4.0'		< 4.0'		
				-			\equiv	Comments:
		Length Y	7.55	≥ 4.0'*1		< 4.0'*1	Ш	nan
		Back of Ramp Obstruction (Y/N)	N	≥ 5.0' * 1		< 5.0'*1		
P	ERPENDICULAR RAMP (PR)	Slope X	2.0	≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y	1.6	≤2.0%		>2.0%		
	Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail	
+	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (n
A	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
T	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	6.05	≥ 4.0'		< 4.0'		Darrell Wyant 52638 Print name clearly Certifica
1	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road			
-	Guitter Flow Glope (as directed)	Horizontal Gaps		≤1/2"		> 1/2"		3J Consulting
		110112011tal Gaps		<u> →1/∠</u>		> 1/ Z		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





