	WASHINGTON COUNTY
	OREGON

ADA Curb Ramp New Construction Inspection Form (Parallel)

OREGON					
NW Curtis St	23885.56		NW Pacif	fic	
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West R		gon.gov/odot/Engineering/Documents
	Calibration Date	7/10/2024 (mm/dd/yy)		_ ,	DA_ExhibitA.pdf for more corner styles. on County corner numbering system.
PL	RAMP RUN 1	Pass	Fail		2
Ramp Style	Running Slope 1	0.5 ≤ 2.0% ■ >	2.0%	Corner	Corner
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	1.6 ≤ 2.0% ■ >	2.0%	Position 3	Positions 2A
depends on the Intersection Control Type. At a	Detectable Warning	N Y	N 🔳	1	* 23
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	≤ 1/4" ■ >	1/4"	3A	1
must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.	Gutter Flow Slope	1.6 ≤ *	>*	2	North
	Curb Running Slope(avg)	5.2 ≤ 8.3% ■ >	8.3%>	4	1
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	8.5 ≤ 5.0% ■ >	5.0%	Pomp.	Positions
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp	Υ	N	Ramp Position	5
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass	Fail		PE Stamp (required for
	Running Slope 2	5.8 ≤ 8.3% ■ >	8.3%		private development)
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Length 2	7.4			
(mets, diignment, etc.)	Cross Slope 2	2.6 ≤ 2.0% >	2.0%		
~ - 4 r	RAMP RUN 3	Pass	Fail		
<i>f T T T T T T T T T T</i>	Running Slope 3	8.5 ≤ 8.3% >	8.3%		
18 Run 3	Length 3	7.45			
Fun 2 But 2	Cross Slope 3	1.4 ≤ 2.0% ■ >	2.0%	Commonto	
Counter slope	TURN SPACE	Pass	Fail	Comments:	
	Width X		< 4.0'	midblock west side, I	טוו
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 ■ <	4.0'*1		
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 ■ <	5.0'*1		
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.6 ≤ 2.0% ■ >	2.0%		
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	0.5 ≤ 2.0% ■ >	2.0%		
Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail	Inspector's Signature	Date (mm/dd/yy
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	5.0 ≥ 4.0' <	< 4.0'	Darrell Wyant	52638
"Il constrained at back of wark, min. 1 length is 5.	Intersection Control Type	SU Slope of Rd.	1.8	Print name clearly	Certification No
Gutter Flow Slope (as directed)	Horizontal Gaps		1/2"	3J Consulting	
			,- <u></u>	Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





