

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

OREGON			<u>•</u>		<u>`</u>		<u> </u>
NW 285th Dr	24952.54				NW S	hadd	don St
North-South Road Name	Project No. Shee	et No. In	tersection N	о.	East-W	est Ro	oad Name
	Calibration Date 8	8 %13 %2024	4 (mm/dd/	' yy)			k - ') · · · · · · · · · · · · · · · · ·
Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner Positions
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Length 1 Cross Slope 1	12.5	≤ 2.0%		>2.0%		Position 3 2A 2
	Detectable Warning (Y,N) Lip Height	N 0	Y 1/4"		N >1/4"		3A North
¹ If Back of Ramp Obstruction is Yes, turn space ength Y must be minimum 5.0 ft.	Gutter Flow Slope Curb Running Slope (avg)	0.9 3.78	≤ * ≤ 8.3%		>* >8.3%		Ramp Positions
² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway. See also Standard Drawings to assess provisions not shown:	Counter Slope (+/-) *2 Longest distance from	5.2	≤ 5.0%		> 5.0%		PE Stamp (required
(inlets, alignment, etc.) Run 1 Counter slope Counter slope	corner to back of curb (see dwg on BT form) Detectable warning extends full width of ramp throat opening	1.3 Y	< 5.0' Y		≥ 5.0' N		private developme
	TURN SPACE LANDING Width X	G NON	E ≥ 4.0'	Pass	< 4.0'	Fail	
	Length Y	5.7	≥ 4.0'*1		< 4.0'*1		Comments: TJITS and j box in TS rr1 icrr
PERPENDICULAR RAMP (PR)	Back of Ramp Obstruction (Y/N) Slope X	N	≥ 5.0'*1 ≤2.0%		< 5.0'*1 >2.0%		
Pedestrian Access Route (to measure Clear Width) Detectable Warning Surface	Slope Y		≤2.0%		>2.0%		
← Cross Slope (2.0% max.) ← Running Slope (8.3% max.)	Flare Slope 1	DIE	≤ 10%	Pass	< 10%	Fail	Inspector's Signature Date (mm,
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Flare Slope 2 Clear Width (feet)		≤ 10% ≥ 4.0'		<10% < 4.0'		Darrell Wyant 52638 Print name clearly Certification
Gutter Flow Slope (as directed)	Intersection Control Type Horizontal Gaps	SY	Slope of ≤1/2"	Road	2.0> 1/2"		3J Consulting Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





