

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	CONT.							
١	IW 288 ter	24952.54				NW m	ays	st
No	orth-South Road Name	Project No. Shee	et No. I	ntersection N	o.	East-W	est Ro	oad Name
		Calibration Date	nan	(mm/dd/	/yy)			k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner
•	ssing value for Gutter Flow Slope (GFS) s on the Intersection Control Type. At a	Length 1	12.5					Position 3 Positions 2A
•	k (MB), GFS must be \leq Slope of the Road, at	Cross Slope 1		≤ 2.0%		>2.0%		3
•	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Υ		N		3A -
5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.		Lip Height		1/4"		>1/4"		2 North
length Y must be minimum 5.0 ft.		Gutter Flow Slope	Δ 1.2	≤ *		>*		
		Curb Running Slope (avg)	3.2	≤ 8.3%		>8.3%		1 Ramp 1 Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	2.7	≤ 5.0%		> 5.0%		Position
	o Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (requii private developr
1	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Y		N		
Counter slope Aun 1 A		TURN SPACE LANDING	G NO	NE 🔳	Pass		Fail	
		Width X	5.35	≥ 4.0'		< 4.0'		
		Length Y	4.8	≥ 4.0'*1		< 4.0'*1	П	Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0' * 1		< 5.0'*1		IITD RR1 ICRR standing ramp
Р	ERPENDICULAR RAMP (PR)	Slope X		≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		
4	Detectable Warning Surface	MISCELLANEOUS Traversa	ble		Pass		Fail	
+	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (
\mathcal{I}	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
T	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 526 Print name clearly Certific
-	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	0.1		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





