| | WASHINGTON COUNTY | |
|---------------------------|---|------------------|
| | OREGON | |
| | Glencoe | |
| | North-South Road Name | |
| | | |
| | | PL |
| | | Ramp Sty |
| depe Mid Roa mus | e passing value for Gutter Flow Slo ends on the Intersection Control T block (MB), GFS must be \leq Slope of d, at Signalized or Uncontrolled (S of the \leq 5.0%, and at Stop ield (SY), GFS must be \leq 2.0%. | ype. At a of the |
| | Back of Ramp Obstruction is Yes, ce length Y must be minimum 5.0 | |
| * ² C and | Clear Space area is the width of Ra extends 4.0 ft into the roadway. | mp Run 1 |

(inlets, alignment, etc.)

18 Run 3

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

ADA Curb Ramp New Construction Inspection Form (Parallel)

24952.54

Ramp Style

| | Project No. Sheet No. | Intersection No. | East- | West F | Road Name | See https://www.oreg | | |
|-----------------------------------|---------------------------------|------------------|--------------|--------|------------------|----------------------|--|------------------|
| | Calibration Date | 9/20/2024 (mm | n/dd/yy) | | | | DA_ExhibitA.pdf for mo n County corner numb | |
| 1 | RAMP RUN 1 | [| Pass | Fail | 3 | 1 111 | | 2 |
| 1 | Running Slope 1 | ≤ 2.0% | > 2.0% | | Corner | - : | Corner Positions | 1 |
| | Cross Slope 1 | 2.3 ≤ 2.0% | > 2.0% | | Position | 3 | 5 | 2A 1 |
| | Detectable Warning | Y | ■ N | | - | 1 | t | 3 |
| | Lip Height | 0 ≤ 1/4" | > 1/4" | | (| 3A | \uparrow | |
| | Gutter Flow Slope | 1.8 ≤ * | > * | | | 2 | North | 2 |
| | Curb Running Slope(avg) | 13.42 ≤ 8.3% | > 8.3%> | | | 4 | Pama (1 | |
| | Counter Slope (+/-)*2 | 6.7 ≤ 5.0% | > 5.0% | | 1 Pama | <u>1</u> 2 | Ramp 1 | |
| | Det. warning full width of ramp | Υ | ■ N | | Ramp Position | | 5 | |
| | RAMP RUN 2 | | Pass | Fail | | | PE Stamp (r | equired for |
| | Running Slope 2 | ≤ 8.3% | > 8.3% | | | | private dev | |
| | Length 2 | 16.4 | | | | | | |
| | Cross Slope 2 | 2.3 ≤ 2.0% | > 2.0% | | | | | |
| | RAMP RUN 3 | | Pass | Fail | | | | |
| | Running Slope 3 | 0.9 ≤ 8.3% | > 8.3% | | | | | |
| | Length 3 | 7.4 | | | | | | |
| | Cross Slope 3 | 1.9 ≤ 2.0% | 2 .0% | | | | | |
| TURN SPACE | | 1 | Pass | | Comment | | | |
| | Width X | 5.0 ≥ 4.0' | ■ <4.0' | | IIITD,gra | ter than2" be | hind curb | |
| | Length Y | 4.95 ≥ 4.0'*1 | < 4.0'*1 | | | | | |
| | Back of Ramp Obstruction (Y/N) | N ≥ 5.0'*1 | < 5.0'*1 | | | | | |
| | Slope X (Cross Slope 1) | 2.3 ≤ 2.0% | > 2.0% | | | | | |
| | Slope Y (Running Slope 1) | ≤ 2.0% | > 2.0% | | | | | |
| MISCELLANEOUS Clear Width (feet) | | | Pass F | | Inspector's S | ignature | | Date (mm/dd/yy |
| | | ≥ 4.0' | < 4.0' | | Darrell \ | | | 52638 |
| | Intersection Control Type | SY Slope o | f Rd. 1.4 | | Print name o | • | | Certification No |
| Horizontal Gaps | | No ≤ 1/2" | > 1/2" | | 3J Consultin | - | | |
| | | | | | | | | |

Cottage



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





