WASHINGTON COUNTY						
OREGON						
NW Timeric						
North-South Road Name						

ADA Curb Ramp New Construction Inspection Form (Parallel)

	INVV TIMERIC	23885.56 NVV Belgii						ium					
North-South Road Name		Project No.	Sheet No.	Intersection No.	E	East-West R	oad Name	See https://www.oregon					
	Calibration Date 7/16/2024 (mm/dd/yy)												
	PL R/	RAMP RUN 1 Pass Fail					2	1		2			
Ramp Style		ınning Slope 1	[≤ 2.0%	> 2.0)%	Corner Position	P	Corner Positions				
The	passing value for Gutter Flow Slope (GFS)	oss Slope 1	L	≤ 2.0%	> 2.0)% [1 03111011	3	5	2A			
•		etectable Warning	Y	N			1	_					
	llock (MB), GFS must be ≤ Slope of the l, at Signalized or Uncontrolled (SU), GFS	Lip Height ≤ 1/4" > 1/4" ■					0	3A 1		o .			
nust be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.		Gutter Flow Slope 0.5 ≤ * ■ > *						2	2				
							2						
¹ If Back of Ramp Obstruction is Yes, turn pace length Y must be minimum 5.0 ft.		urb Running Slope(av	vg)	9.92 ≤ 8.3%	<u> </u>	3%> 🔳 │		Ramp 1	1				
		Counter Slope (+/-)*2					2 F	Positions					
Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		et. warning full width	n of ramp	Y	N		Ramp Position		5				
		RAMP RUN 2 Pass Fail							PE Stamp	(required for			
	Ru	ınning Slope 2	L	≤ 8.3%	> 8.3	3%			private de	evelopment)			
See also Standard Drawings to assess provisions not shown:		ength 2	[6									
(iniet	cs, alignment, etc.)	oss Slope 2	[3.9 ≤ 2.0%	> 2.0	0% 🔳							
	R/	RAMP RUN 3 Pass Fail											
Counter slope PARALLEL RAMP (PL)		Running Slope 3 ≤ 8.3% > 8.3%				3%							
		ength 3	[7.95									
		oss Slope 3	Γ	3.3 ≤ 2.0%	> 2.	0% 🔳							
		TURN SPACE Pass Fai				Fail	Comments:						
		idth X	[3.45 ≥ 4.0'	< 4.	.0'	NTD Fail	D Fail RR 1 And TS					
		ength Y	[5.0 ≥ 4.0'*	¹ = < 4.0	0'*1							
	PARALLEL RAMP (PL)	ck of Ramp Obstruction	(Y/N)	≥ 5.0'*	1 < 5.0	0'*1							
	Pedestrian Access Route (to measure Clear Width)	ope X (Cross Slope 1)	[≤ 2.0%	> 2.0	0% 🔲							
	Detectable Warning Surface Cross Slope (2.0% max.)	ope Y (Running Slope 1)	[≤ 2.0%	> 2.0	0%							
		MISCELLANEOUS Pass Fail					Inspector's Signature Date (n						
	Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	ear Width (feet)	[3.45 ≥ 4.0'	< 4.	.0'	Darrell W	·		52638			
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	tersection Control Typ	oe	SY Slope of	of Rd. 0.5	5	Print name clearly Cert			Certification No			
	Gutter Flow Slope (as directed)	orizontal Gaps	Ē	o ≤ 1/2"			3J Consulting	-					
	'''			-,-			Company/Age	encv					



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





