WASHINGTON COUNTY OREGON	ADA	Curb Ramp New Const	ruction Inspection	Form (Para	allel)			
		23885.56						
North-South Road Name		Project No. Sheet No.	. Intersection No.	East-West F	Road Name See https://www.or	egon.gov/odot/Engineering/Documen		
		Calibration Date	(mm/dd/yy		_RoadwayEng/ <i>A</i>	ADA_ExhibitA.pdf for more corner style on County corner numbering system.		
	PL	RAMP RUN 1	Pass	Fail				
	Ramp Style	Running Slope 1	≤ 2.0%	> 2.0%	Corner	Corner		
*The massing value for Cuttor Flavy Cl		Cross Slope 1	≤ 2.0%	> 2.0%	Position 3	Positions 2A		
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%. *1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		·	V	N	1	2		
		Detectable Warning			1	3		
		Lip Height	≤ 1/4" ■	> 1/4"	3A			
		Gutter Flow Slope	1.7 ≤ *	>*	2	North		
		Curb Running Slope(avg)	4.58 ≤ 8.3%	> 8.3%>		(F)		
		Counter Slope (+/-)*2	3.9 ≤ 5.0% ■		4	Ramp 1		
$*^2$ Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		Det. warning full width of ram		N	Ramp	5		
		RAMP RUN 2	Pass		Position	DE Channa (naminal fam		
		Running Slope 2	5.6 ≤ 8.3%			PE Stamp (required for private development)		
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		Length 2	7.1					
		Cross Slope 2	0.8 ≤ 2.0%	> 2.0%				
		RAMP RUN 3	Pass					
of Run 3		Running Slope 3	9.2 ≤ 8.3%	> 8.3%				
		Length 3	7.5					
		Cross Slope 3	≤ 2.0%	> 2.0%				
Counter slope Counter flow slope		TURN SPACE			Comments:	nments:		
			Pass 5.0 ≥ 4.0'	< 4.0'	DWS IITD Fails turn	S IITD Fails turn space, RR to		
		Width X Length Y			nowhere	•		
PARALLEL RAMP (PL)	PARALLEL RAMP (PL)		5.0 ≥ 4.0'*1 ■	< 4.0'*1				
PARALLEL RAMP (PL)		Back of Ramp Obstruction (Y/N)	≥ 5.0'*1	< 5.0'*1				
Pedestrian Access Route (to measure Clea	r Width)	Slope X (Cross Slope 1)	≤ 2.0%	> 2.0%				
Detectable Warning Surface Cross Slope (2.0% max.)		Slope Y (Running Slope 1)	≤ 2.0%	> 2.0%				
Running Slope (8.3% max.) Counter Slope (5.0% max.)		MISCELLANEOUS	Pass	Fail	Inspector's Signature	Date (mm/d		
					- II 147			

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

Clear Width (feet)

Horizontal Gaps

Intersection Control Type

≥ 4.0'

< 4.0'

Slope of Rd. 0.3

≤ 1/2" ■ > 1/2"

52638

Certification No.

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





