	WASHINGTON COUNTY
	OREGON

ADA Curb Ramp New Construction Inspection Form (Parallel)

OREGON					
NW Curtis	23885.56 NW Pacific				
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West F	• • • •	gon.gov/odot/Engineering/Documents
	Calibration Date	06/05/24 (mm/dd/	yy)	_RoadwayEng/ADA_ExhibitA.pdf for more corne Use Washington County corner numbering sys	
	RAMP RUN 1	Pas	s Fail		
PL		1.7 ≤ 2.0%		1	Corner
Ramp Style	Running Slope 1	1.7 S 2.0%	2.0%	Corner Position	Positions 1
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	1.7 ≤ 2.0%	l > 2.0%	Position 3	5 2A
depends on the Intersection Control Type. At a	Detectable Warning	N Y	N 🔳	1	
Midblock (MB), GFS must be ≤ Slope of the	Lip Height	≤ 1/4" ■	 > 1/4"	1	↑
noad, at signalized of official office (50), dis				3A	North
must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.	Gutter Flow Slope	0.7 ≤ *	> *	1	2
or field (31), GF3 mast be ≤ 2.0%.	Curb Running Slope(avg)	7.18 ≤ 8.3%	l > 8.3%>		(1)
1 If Back of Ramp Obstruction is Yes, turn	Countar Clana (1 /)?	5.5 ≤ 5.0%	> 5.0%	1 4	Ramp 1
	Counter Slope (+/-)*2		: =1	Ramp	Positions
== Clear Space area is the width of Ramp Run 1 ===	Det. warning full width of ramp		N L	Position	
	RAMP RUN 2	Pas			PE Stamp (required for
-	Running Slope 2	≤ 8.3%	> 8.3%		private development)
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Length 2	7.6			
(mets, diignment, etc.)	Cross Slope 2	2.3 ≤ 2.0%	」> 2.0% ■		
The second secon	RAMP RUN 3	Pas	s Fail		
	Running Slope 3	5.6 ≤ 8.3%	l > 8.3%		
Brun 3	Length 3	7.7			
Assessment / num c //	Cross Slope 3	1.6 ≤ 2.0%	I > 2.0% □		
Counter slope Gutter flow store	·			Comments:	
	TURN SPACE	Pas		midblock east side	
	Width X	5.0 ≥ 4.0'	< 4.0'	I I I I I I I I I I I I I I I I I I I	
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1	< 4.0'*1		
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1	< 5.0'*1		
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.7 ≤ 2.0%	> 2.0%		
Detectable Warning Surface	Slope Y (Running Slope 1)	1.7 ≤ 2.0%	> 2.0%		06/05/24
Cross Slope (2.0% max.)	MISCELLANEOUS	Pas		Inspector's Signature	Date (mm/dd/yy
Counter Slope (5.0% max.)					
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* *If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	5.0 ≥ 4.0'	< 4.0'	Darrell Wyant Print name clearly	52638 Certification No
Gutter Flow Slope (as directed)	Intersection Control Type	Slope of Ro	d. 1.0		Cerunication No
	Horizontal Gaps	≤ 1/2"	> 1/2"	3J Consulting	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





