Main	24952.54	Hillo	crest	
North-South Road Name	Project No. Sheet No.	o. Intersection No. East-N	West Road Name	See https://www.oregon.gov/odot/Engineering/Documents
	Calibration Date	10/8/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more corner style: Use Washington County corner numbering system.
PL	RAMP RUN 1	Pass	Fail 4	
Ramp Style	Running Slope 1	≤ 2.0% > 2.0%	Corner	Corner Positions
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	6.6 ≤ 2.0% > 2.0%	Position	3 5 2A
depends on the Intersection Control Type. At a	Detectable Warning	Y Y N		
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" ■ > 1/4"		3A -
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	3.7 ≤ * > *		North
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	9.26 ≤ 8.3% > 8.3%>		
* ¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	12.2 ≤ 5.0% ■ > 5.0%	1	4 Ramp 1 Positions
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Det. warning full width of ram	p Y N	Ramp Position	5
	RAMP RUN 2	Pass	Fail	PE Stamp (required for
	Running Slope 2	≤ 8.3% > 8.3%		private development)
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Length 2			
	Cross Slope 2	≤ 2.0% > 2.0%		
Counter slope Counter slope Counter slope	RAMP RUN 3	Pass	Fail	
	Running Slope 3	9.4 ≤ 8.3% > 8.3%		
	Length 3	7.25		
	Cross Slope 3	≤ 2.0% > 2.0%		
	TURN SPACE	Pass	Fail	
	Width X	4.8 ≥ 4.0'	UIIID gt	IITD gt2. R2 gravel parking lot.
PARALLEL RAMP (PL)	Length Y	6.15 ≥ 4.0'*1 ■ < 4.0'*1		
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 < 5.0'*1		
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	6.6 < 2.0% > 2.0%		

Detectable Warning Surface

Cross Slope (2.0% max.)

← Running Slope (8.3% max.)

Counter Slope (5.0% max.)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

4.8

SY

≤ 2.0%

≥ 4.0'

> 2.0%

< 4.0'

Pass

Slope of Rd. 3.1

≤ 1/2" ■ > 1/2"

Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting

Date (mm/dd/yy)

52638

Certification No.

Slope Y (Running Slope 1)

MISCELLANEOUS

Clear Width (feet)

Horizontal Gaps

Intersection Control Type



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





