

## **ADA Curb Ramp New Construction Inspection Form (Perpendicular)**

-	- Catch							
N	lw 292	24952.54				Nw w	est u	nion
No	orth-South Road Name	Project No. Shee	et No. In	tersection N	o.	East-W	est Ro	pad Name
		Calibration Date	8/6/2024	(mm/dd,	/yy)			k - ') · · · · · · · · · · · · · · · · ·
	Ramp Style PR	RAMP RUN 1	5.0	≤ 8.3%	Pass	>8.3%	Fail	1 Corner
	ssing value for Gutter Flow Slope (GFS) Is on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Running Slope 1 Length 1	8.35	_ = 0.070				Corner Position 3 Positions 2A
•		Cross Slope 1		≤ 2.0%		>2.0%		
•	ed or Uncontrolled (SU), GFS must be ≤ and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Detectable Warning (Y,N) Lip Height		Y 1/4"		N >1/4"		3A North
	must be minimum 5.0 ft.	Gutter Flow Slope	2.1	1/4 ≤ *		>1/4 >*		
		Curb Running Slope (avg)  Counter Slope (+/-) *2	3.98	≤ 8.3%		>8.3%		Ramp Position
	4.0 ft into the roadway.  Standard Drawings to assess provisions not shown:	Longest distance from	2.6	≤ 5.0%		> 5.0%		PE Stamp (required private developme
(inlets,	alignment, etc.)	corner to back of curb (see dwg on BT form)	0.6	< 5.0'		≥ 5.0'	Ш	private developme
A Sur		Detectable warning extends full width of ramp throat opening		Υ		N		
		TURN SPACE LANDING	G NON	E	Pass		Fail	
		Width X	4.7	≥ 4.0'		< 4.0'		
		Length Y	5.6	≥ 4.0'*1		< 4.0'*1		IITD not full width rr1 icrr
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'* <sup>1</sup>	Ш	
P	ERPENDICULAR RAMP (PR)  Pedestrian Access Route (to measure Clear Width)	Slope X	10.8	≤2.0%		>2.0%		
	Detectable Warning Surface	Slope Y		≤2.0%		>2.0%		
<b></b>	Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	ble		Pass		Fail	
<b>←</b>	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mm
1	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
<b>I</b>	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 5263 Print name clearly Certificat
-	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	2.1		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





