

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

- Courty							
NW 289th Ave	24952.54				NW C	arve	er St
North-South Road Name	Project No. Shee	et No. Ir	ntersection N	о.	East-W	est Ro	oad Name
	Calibration Date	8/6/2024	(mm/dd/	′ yy)			k - ¹) ² - ² · · · · · · · · · · · · · · · · ·
Ramp Style PR	RAMP RUN 1	10.1	≤ 8.3%	Pass	>8.3%	Fail	Corner
The passing value for Gutter Flow Slope (GFS)	Running Slope 1 Length 1	10.0	0.5%		7 0.370		Corner Position 3 Positions 2A
depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, a	Cross Slope 1		≤ 2.0%		>2.0%		
signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%	Detectable Warning (Y,N) Lip Height	Υ	Υ		N	Ш	3A North
¹ If Back of Ramp Obstruction is Yes, turn space	Gutter Flow Slope	1.1	1/4" ≤ *		>1/4" >*		
ength Y must be minimum 5.0 ft. ² Clear Space area is the width of Ramp Run 1 and	Curb Running Slope (avg)	2.64	≤ 8.3%		>8.3%		1 Ramp 1 Positions
extends 4.0 ft into the roadway.	Counter Slope (+/-) *2	4.8	≤ 5.0%		> 5.0%		Position De Stamp (requir
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	2.0	< 5.0'		≥ 5.0'		private developr
Counter slope X To X T	Detectable warning extends full width of ramp throat opening	Υ	Y		N		
	TURN SPACE LANDIN	G NON	IE	Pass		Fail	
	Width X	1.9	≥ 4.0'		< 4.0'		
	Length Y	3.1	≥ 4.0'*1		< 4.0'*1		Comments:
	Back of Ramp Obstruction (Y/N)	N	≥ 5.0'*1		< 5.0'* ¹		1
PERPENDICULAR RAMP (PR)	Slope X	10.1	≤2.0%		>2.0%		
Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		L
Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	able		Pass		Fail	
Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (i
Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 5263 Print name clearly Certific
Gutter Flow Slope (as directed)	Intersection Control Type	SU	Slope of	Road	0.1		3J Consulting
	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





