

## **ADA Curb Ramp New Construction Inspection Form (Perpendicular)**

,	√w Jackson	24952.54				Nw m	21/2	
	orth-South Road Name		et No. In	tersection N	0.			pad Name
. • •			8/13/2024	_		2030 00		o k - ')' - ' ' ' ' ' ' '
							y ‡ # · · · ·	
	Ramp Style PR	RAMP RUN 1 Running Slope 1	6.6	≤ 8.3%	Pass	>8.3%	Fail	Corner Positions
The pas	sing value for Gutter Flow Slope (GFS)	Length 1	14.65					Position 3 Positions 2A
'	ds on the Intersection Control Type. At a ock (MB), GFS must be $\leq$ Slope of the Road, at	Cross Slope 1	1.3	≤ 2.0%		>2.0%		203
Signalize	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Υ		N		3A
5.0%, and at Stop or Yield (SY), GFS must be $\leq$ 2.0%.		Lip Height		1/4"		>1/4"		North
	k of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope	1.1	≤ *		>*		4
		Curb Running Slope (avg)	5.8	≤ 8.3%		>8.3%		1 Ramp Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	6.1	≤ 5.0%		> 5.0%		Position 5
	o Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (required private developmer
Counter slope		Detectable warning extends full width of ramp throat opening		Υ		N		
		TURN SPACE LANDING	G NON	E	Pass		Fail	
		Width X	3.7	≥ 4.0'		< 4.0'		
		Length Y	5.3	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0' <b>*</b> 1		< 5.0'*1		
P	Service and the place of the service	Slope X		≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		
<b>=</b>	Detectable Warning Surface  Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	able		Pass		Fail	
<b>4</b>	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mm/
1	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	3.7	≥ 4.0'		< 4.0'		Darrell Wyant 52638 Print name clearly Certification
-	Gutter Flow Slope (as directed)	Intersection Control Type	SU	Slope of	Road	1.4		3J Consulting
	contracts on the charge of the production of the opening of the charge o	Horizontal Gaps		· ≤1/2"		> 1/2"		Company/Agency



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





