	WASHINGTON COUNTY	1					
	OREGON						
	NW 309th Ave						
	North-South Road Name						
		PL					
		Ramp Sty					
dep Mid Roa mus	*The passing value for Gutter Flow Slope (GFS depends on the Intersection Control Type. At Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.						
	f Back of Ramp Obstruction is Ye ce length Y must be minimum 5.						

(inlets, alignment, etc.)

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

24952.54

 $^{*2}$  Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

**Detectable Warning Surface** Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)\*
\* If constrained at back of walk, min. Y length is 5'.

Ramp Style

	Project No. Sheet No.	Intersection N	lo.	East-\	Nest F	Road Name	See https://www.ore		
	Calibration Date	10/22/2024	0/22/2024 (mm/dd/yy)				_RoadwayEng/ADA_ExhibitA.pdf for more corner styles. Use Washington County corner numbering system.		
1	RAMP RUN 1		Pass		Fail	2	1 111	70.0	2
1	Running Slope 1	≤ 2.0	)%	2.0%		Corner Position		Corner Positions	0
	Cross Slope 1	4.1 ≤ 2.0	)%	2.0%		POSITION	3	5	2A 1
	Detectable Warning	N Y		N		_	1		3
	Lip Height	1.0 ≤ 1/	<b>'4"</b>	1/4"		(	3A -	1	
	Gutter Flow Slope	1.7 ≤ *		> *		ì	2	North	2
	Curb Running Slope(avg)	9.78 ≤ 8.3	3% >	8.3%>		=	4		(1)
	Counter Slope (+/-)*2	5.9 ≤ 5.0	%	5.0%		1	12	Ramp <sub>1</sub> Positions	
	Det. warning full width of ramp	N Y		N		Ramp Position		5	
	RAMP RUN 2		Pass		Fail			PE Stamp	(required for
	Running Slope 2	≤ 8.3	3% >	8.3%					evelopment)
	Length 2	7.3							
	Cross Slope 2	4.2 ≤ 2.0	)%	2.0%					
	RAMP RUN 3		Pass		Fail				
	Running Slope 3	≤ 8.3	3% 🗌 >	8.3%					
	Length 3	7.25							
	Cross Slope 3	4.3 ≤ 2.0	)% 🔲 >	2.0%					
	TURN SPACE		Pass			Comments	): 		
	Width X	3.85 ≥ 4.0	0'	< 4.0'					
	Length Y	5.0 ≥ 4.0	'*¹ <b>■</b> <	4.0'*1					
	Back of Ramp Obstruction (Y/N)	N ≥ 5.0	·*1 <b>(</b>	5.0'*1					
	Slope X (Cross Slope 1)	4.1 ≤ 2.0	%	2.0%					
	Slope Y (Running Slope 1)	≤ 2.0	%	2.0%					
	MISCELLANEOUS		Pass		Fail	Inspector's Si	ignature		Date (mm/dd/yy)
	Clear Width (feet)	≥ 4.0	)'	< 4.0'		Darrell V	•		52638
	Intersection Control Type	SY Slope	e of Rd.	1.4		Print name cl	· ·		Certification No
	Horizontal Gaps		1/2"		3J Consultir				
	·			•		Company/Ag	encv		

NW Brooking Ct

**Reset Entire Form** 

**Keep Intersection, Reset Fields** 



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





