


ADA Curb Ramp New Construction Inspection Form (Perpendicular)

Nw 289 ave	24952.54				N Kee	enon s	st
North-South Road Name	Project No. Shee	et No. In	tersection N	o.	East-W	est Ro	oad Name
	Calibration Date	8/6/2024	(mm/dd,	/yy)			k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR	RAMP RUN 1 Running Slope 1	3.8	≤ 8.3%	Pass	>8.3%	Fail	2 Corner
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤	Length 1 Cross Slope 1 Detectable Warning (Y,N)	0.7	≤ 2.0% Y		>2.0% N		Corner Positions Positions 2A 3A
5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height		1/4"		>1/4"		2 North
¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Gutter Flow Slope		≤ *		>*		1 A Ramp 1
² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Curb Running Slope (avg) Counter Slope (+/-) *2	5.5	≤ 8.3% ≤ 5.0%		>8.3% > 5.0%		Ramp Position
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	1.5	< 5.0'		≥ 5.0'		PE Stamp (requir private developn
Aun 1	Detectable warning extends full width of ramp throat opening		Υ		N		
	TURN SPACE LANDING	G NON	E	Pass		Fail	
	Width X	5.3	≥ 4.0'		< 4.0'		
Counter slope Guiler Flow slope	Length Y	5.4	≥ 4.0'*1		< 4.0'*1		Comments:
	Back of Ramp Obstruction (Y/N)		≥ 5.0' * ¹		< 5.0'*1		
PERPENDICULAR RAMP (PR)	Slope X	2.3	≤2.0%		>2.0%		
Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		
Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	able		Pass		Fail	
Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (n
Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Darrell Wyant 5263
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Print name clearly Certification
Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	1.5		3J Consulting
	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





