	WASHINGTON COUNTY
	OREGON

## **ADA Curb Ramp New Construction Inspection Form (Blended Transition)**

	NW. EMPRESS PL.	24953	NW.	NORTH AVE		
	North-South Road Name	Project No. Sheet No.  Calibration Date 10	Intersection No. East-W 0/9/2024 (mm/dd/yy)	Vest Road Name	_RoadwayEng/ADA_Exhil	/odot/Engineering/Documents bitA. for more corner styles. corner numbering system.
depend Midblo Signaliz 5.0%, a * <sup>1</sup> Clea extend	BT Ramp Style  assing value for Gutter Flow Slope (GFS) ds on the Intersection Condition Type. At a ack (MB), GFS must be ≤ Slope of the Road, at aced or Uncontrolled (SU), GFS must be ≤ and at Stop or Yield (SY), GFS must be ≤ 2.0%.  The Space area is the width of Ramp Run 1 and as 4.0 ft into the roadway.  Standard Drawings to assess provisions not shown: lignment, etc.)  BLENDED TRANSITION (BT)  Pedestrian access route (To measure clear width)	Counter Slope (+/- )*1  Ramp Width  Longest distance from DW Corner to back of curb (to nearest inch)  DW extends full width of ramp throat opening  Both er grade by 5.0 ft from the by grade by greater	Y ■  1.2 ≤*  3.23 ≤ 8.3% ■ :  4.3 ≤  5.0%  ■ >	Fail  >2.0%  N  >1/4"  >*  >8.3%  > 5.0%   N	Comments:	PE Stamp (required for private development)
	Detectable warning surface	MISCELLANEOUS Traversabl	e Pass	Fail		
4		Flare Slope 1	≤ 10%	>10%		
***	Running slope (<5.0% finish grade max.) (If running slope ≥5.0%, this is a curb ramp, not a blended transition.)	Flare Slope 2	≤ 10%	>10%	Inspector's Signature	Date (mm/dd/yy
4	Counter slope (5.0% finish grade max.)	Clear Width (feet)	≥ 4.0'	< 4.0'	Darrell Wyant	52638.0
+	Gutter flow slope (as required)	Horizontal Gaps	≤ 1/2"	>1/2"	Print name clearly	Certification No
-	Edge of Gutter Pan	Intersection Control Type	SY Slope of Ro	oad 1.5	3J Consulting Company/Agency	



## **ADA Curb Ramp Images**

Blended Transitions are locations where the pedestrian walkway (which has one direction of travel) and the street crossing intersect at the same plane without the need of a ramp. If the Running Slope is 5.0% or more, the ramp is not a Blended Transition and should be inspected using a different inspection form.

Attached photos must be in .pdf format in order to be placed



