WASHINGTON COUNTY OREGON ADA	A Curb Ramp New Const	ruction Inspection Form (Par	allel)
Nw 313	24952.54	Nw cotta	age
North-South Road Name	Project No. Sheet No. Calibration Date	Edst West	Road Name See https://www.oregon.gov/odot/Engineering/Docume _RoadwayEng/ADA_ExhibitA.pdf for more corner sty Use Washington County corner numbering system
	RAMP RUN 1	Pass Fail	
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Running Slope 1	1.7 ≤ 2.0% ■ > 2.0%	Corner
	Cross Slope 1	≤ 2.0% > 2.0%	Position 3 Positions 2A
	Detectable Warning	Y N	2
	Lip Height	0 ≤ 1/4" > 1/4"	3A -
	Gutter Flow Slope	1.7	North 2
	Curb Running Slope(avg)	3.46 ≤ 8.3% ■ > 8.3%>	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	4.5 ≤ 5.0% ■ > 5.0%	2 Ramp Positions 1
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Det. warning full width of ram		Position 5
	RAMP RUN 2	Pass Fail	PE Stamp (required fo
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Running Slope 2	8.05 ≤ 8.3% ■ > 8.3%	private development
	Length 2	6.5	
	Cross Slope 2	2 ≤ 2.0% ■ > 2.0%	
Counter slope Counter slope Counter slope	RAMP RUN 3	Pass Fail	
	Running Slope 3	1.9 ≤ 8.3% ■ > 8.3%	
	Length 3	10	
	Cross Slope 3	1.6 ≤ 2.0% ■ > 2.0%	
	TURN SPACE	Pass Fail	Comments:
	Width X	5.0 ≥ 4.0' ■ < 4.0'	
PARALLEL RAMP (PL)	Length Y	4.75 ≥ 4.0'*1 ■ < 4.0'*1	
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 < 5.0'*1	

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Detectable Warning Surface

Cross Slope (2.0% max.)

Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

Slope X (Cross Slope 1)

MISCELLANEOUS

Clear Width (feet)

Horizontal Gaps

Intersection Control Type

Slope Y (Running Slope 1)

1.7

5.0

SY

≤ 2.0%

≤ 2.0%

≥ 4.0'

≤ 1/2"

Slope of Rd.

> 2.0%

> 2.0%

< 4.0'

1/2"

Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting

Pass

Date (mm/dd/yy)

Certification No.

52638



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





